

Mission Sim 1 Timeline

Test Time	S/C UTC	S/C MET	Dt	Command
2001-DEC-4/09:59:59	2003-317/09:59:59	43235935		MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN",0,593
2001-DEC-4/09:59:59	2003-317/09:59:59	43235935	0	RF_BEAM_2 "OFF"
2001-DEC-4/09:59:59	2003-317/09:59:59	43235935	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-4/09:59:59	2003-317/09:59:59	43235935	0	RF_TWT_2_PWR "OFF"
2001-DEC-4/10:00:00	2003-317/10:00:00	43235936	1	RF_BEAM_1 "OFF"
2001-DEC-4/10:00:01	2003-317/10:00:01	43235937	1	RF_SW_TO_SW_SEL "SW1_TO_SW3"
2001-DEC-4/10:00:01	2003-317/10:00:01	43235937	0	RF_SW3_SEL_ANT "FLGA"
2001-DEC-4/10:00:01	2003-317/10:00:01	43235937	0	RF_SW2_SEL_ANT "PANCAKE"
2001-DEC-4/10:00:01	2003-317/10:00:01	43235937	0	I1_RF_EXCITER "ON"
2001-DEC-4/10:00:02	2003-317/10:00:02	43235938	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-4/10:00:02	2003-317/10:00:02	43235938	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-4/10:00:02	2003-317/10:00:02	43235938	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-4/10:00:02	2003-317/10:00:02	43235938	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-4/10:00:03	2003-317/10:00:03	43235939	1	EXECUTE_MACRO "OBB_SIDE_1_FLGA_PAN_B"
2001-DEC-4/10:00:03	2003-317/10:00:03	43235939	0	MACRO_END
2001-DEC-4/10:00:03	2003-317/10:00:03	43235939	0	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN_B",0,594
2001-DEC-4/10:00:03	2003-317/10:00:03	43235939	0	CD_DL_RATE_SEL "12.5HZ"
2001-DEC-4/10:00:03	2003-317/10:00:03	43235939	0	CD_DL_SUBC_MOD_ST_SEL "ON"
2001-DEC-4/10:00:03	2003-317/10:00:03	43235939	0	CD_DL_MOD_INDX_SEL "LOW"
2001-DEC-4/10:00:03	2003-317/10:00:03	43235939	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-4/10:00:04	2003-317/10:00:04	43235940	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-4/10:00:05	2003-317/10:00:05	43235941	1	CD_DL_SRC_SEL "RT"
2001-DEC-4/10:00:06	2003-317/10:00:06	43235942	1	RF_TWT_1_PWR "ON"
2001-DEC-4/10:00:07	2003-317/10:00:07	43235943	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-4/10:04:08	2003-317/10:04:08	43236184	241	RF_BEAM_1 "ON"
2001-DEC-4/10:04:08	2003-317/10:04:08	43236184	0	MACRO_END
2001-DEC-4/10:04:09	2003-317/10:04:09	43236185	1	MACRO_START "CDH","OBB_LO_TLM_RATES_1",0,604
2001-DEC-4/10:04:09	2003-317/10:04:09	43236185	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/10:04:09	2003-317/10:04:09	43236185	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/10:04:09	2003-317/10:04:09	43236185	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/10:04:09	2003-317/10:04:09	43236185	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/10:04:09	2003-317/10:04:09	43236185	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/10:04:10	2003-317/10:04:10	43236186	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/10:04:10	2003-317/10:04:10	43236186	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/10:04:10	2003-317/10:04:10	43236186	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/10:04:10	2003-317/10:04:10	43236186	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/10:04:10	2003-317/10:04:10	43236186	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/10:04:10	2003-317/10:04:10	43236186	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/10:04:10	2003-317/10:04:10	43236186	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/10:04:10	2003-317/10:04:10	43236186	0	MACRO_END
2001-DEC-4/10:05:59	2003-317/10:05:59	43236295	109	CD_TLM_PKT_PROD "ESS_PKT","PROD_INDEP_RATE",1

Mission Sim 1 Timeline

2001-DEC-4/10:05:59	2003-317/10:05:59	43236295	0	CD_TLM_PKT_PROD "NAV_PKT","PROD_INDEP_RATE",1
2001-DEC-4/10:11:59	2003-317/10:11:59	43236655	360	CD_INSTR_CH_SEL 7
2001-DEC-4/10:11:59	2003-317/10:11:59	43236655	0	CD_INSTR_ALWD_PKT_CNT "IMAGER",6800
2001-DEC-4/10:11:59	2003-317/10:11:59	43236655	0	CD_INSTR_ALWD_PKT_CNT "CRISP",100
2001-DEC-4/10:11:59	2003-317/10:11:59	43236655	0	CD_INSTR_ALWD_PKT_CNT "CIDA",100
2001-DEC-4/10:11:59	2003-317/10:11:59	43236655	0	CD_IMAG_SEL "CFI"
2001-DEC-4/10:17:59	2003-317/10:17:59	43237015	360	USE_REDUNDANT_SS "SSR"
2001-DEC-4/10:17:59	2003-317/10:17:59	43237015	0	CD_INSTR_CH_SEL 7
2001-DEC-4/10:17:59	2003-317/10:17:59	43237015	0	CD_INSTR_ALWD_PKT_CNT "IMAGER",6800
2001-DEC-4/10:17:59	2003-317/10:17:59	43237015	0	CD_INSTR_ALWD_PKT_CNT "CRISP",100
2001-DEC-4/10:17:59	2003-317/10:17:59	43237015	0	CD_INSTR_ALWD_PKT_CNT "CIDA",100
2001-DEC-4/10:17:59	2003-317/10:17:59	43237015	0	CD_IMAG_SEL "CFI"
2001-DEC-4/10:17:59	2003-317/10:17:59	43237015	0	USE_PRIMARY_SS "SSR"
2001-DEC-4/10:23:59	2003-317/10:23:59	43237375	360	SSR_PTR_SET "LOW",11264
2001-DEC-4/10:23:59	2003-317/10:23:59	43237375	0	SSR_LO_RCRD_CTL "CONT",0
2001-DEC-4/10:24:00	2003-317/10:24:00	43237376	1	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-4/10:24:59	2003-317/10:24:59	43237435	59	MACRO_START "CDH","OBB_ASPIN_3AXIS",0,988
2001-DEC-4/10:24:59	2003-317/10:24:59	43237435	0	PS_PRI_TLM_PROP "ON"
2001-DEC-4/10:25:00	2003-317/10:25:00	43237436	1	PS_SEC_TLM_PROP "ON"
2001-DEC-4/10:25:01	2003-317/10:25:01	43237437	1	PRI_SPINUP_CAT_HTR "ON"
2001-DEC-4/10:25:02	2003-317/10:25:02	43237438	1	PRI_SPINDN_CAT_HTR "ON"
2001-DEC-4/10:25:03	2003-317/10:25:03	43237439	1	PRI_RADIAL_CAT_HTR "ON"
2001-DEC-4/10:25:04	2003-317/10:25:04	43237440	1	PRI_DV_CAT_HTR "OFF"
2001-DEC-4/10:25:05	2003-317/10:25:05	43237441	1	SEC_SPINUP_CAT_HTR "ON"
2001-DEC-4/10:25:06	2003-317/10:25:06	43237442	1	SEC_SPINDN_CAT_HTR "ON"
2001-DEC-4/10:25:07	2003-317/10:25:07	43237443	1	SEC_RADIAL_CAT_HTR "ON"
2001-DEC-4/10:25:08	2003-317/10:25:08	43237444	1	SEC_DV_CAT_HTR "OFF"
2001-DEC-4/10:25:09	2003-317/10:25:09	43237445	1	PRI_AD_THRUST_HTR "ON"
2001-DEC-4/10:25:10	2003-317/10:25:10	43237446	1	PRI_BC_THRUST_HTR "ON"
2001-DEC-4/10:25:11	2003-317/10:25:11	43237447	1	SEC_AD_THRUST_HTR "ON"
2001-DEC-4/10:25:12	2003-317/10:25:12	43237448	1	SEC_BC_THRUST_HTR "ON"
2001-DEC-4/10:25:13	2003-317/10:25:13	43237449	1	PRI_LV_LINE_HTR_HI "ON"
2001-DEC-4/10:25:14	2003-317/10:25:14	43237450	1	SEC_LV_LINE_HTR_HI "ON"
2001-DEC-4/10:25:15	2003-317/10:25:15	43237451	1	PRI_LV_LINE_HTR_LO "ON"
2001-DEC-4/10:25:16	2003-317/10:25:16	43237452	1	SEC_LV_LINE_HTR_LO "ON"
2001-DEC-4/10:25:17	2003-317/10:25:17	43237453	1	PRI_SC_SV_HTR "ON"
2001-DEC-4/10:25:18	2003-317/10:25:18	43237454	1	SEC_SC_SV_HTR "ON"
2001-DEC-4/10:25:19	2003-317/10:25:19	43237455	1	PRI_TANK_HTR "ON"
2001-DEC-4/10:25:20	2003-317/10:25:20	43237456	1	SEC_TANK_HTR "ON"
2001-DEC-4/10:25:21	2003-317/10:25:21	43237457	1	ESS_PWR "ON"
2001-DEC-4/10:25:22	2003-317/10:25:22	43237458	1	ST_PWR "ON"
2001-DEC-4/10:25:23	2003-317/10:25:23	43237459	1	GYRO_PWR "ON"
2001-DEC-4/10:26:08	2003-317/10:26:08	43237504	45	I1_GC1_PWR "ON"
2001-DEC-4/10:26:09	2003-317/10:26:09	43237505	1	I2_GC2_PWR "ON"

Mission Sim 1 Timeline

2001-DEC-4/11:31:29	2003-317/11:31:29	43241425	5	CFI_IMG_PWR "ON","EXECUTE"
2001-DEC-4/11:53:59	2003-317/11:53:59	43242775	1350	GC_ADD_TLM 1,256
2001-DEC-4/11:53:59	2003-317/11:53:59	43242775	0	CD_GC_SCEN_SEL 3
2001-DEC-4/11:54:00	2003-317/11:54:00	43242776	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-4/11:54:15	2003-317/11:54:15	43242791	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-4/11:58:59	2003-317/11:58:59	43243075	284	GC_ADD_TLM 0,0
2001-DEC-4/11:59:00	2003-317/11:59:00	43243076	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-4/11:59:00	2003-317/11:59:00	43243076	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-4/11:59:01	2003-317/11:59:01	43243077	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-4/11:59:02	2003-317/11:59:02	43243078	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/11:59:02	2003-317/11:59:02	43243078	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-4/11:59:02	2003-317/11:59:02	43243078	0	USE_PRIMARY_SS "GNC"
2001-DEC-4/11:59:02	2003-317/11:59:02	43243078	0	MACRO_END
2001-DEC-4/12:00:29	2003-317/12:00:29	43243165	87	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA",0,597
2001-DEC-4/12:00:29	2003-317/12:00:29	43243165	0	RF_BEAM_2 "OFF"
2001-DEC-4/12:00:29	2003-317/12:00:29	43243165	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-4/12:00:29	2003-317/12:00:29	43243165	0	RF_TWT_2_PWR "OFF"
2001-DEC-4/12:00:30	2003-317/12:00:30	43243166	1	RF_BEAM_1 "OFF"
2001-DEC-4/12:00:31	2003-317/12:00:31	43243167	1	RF_SW1_SEL_ANT "HGA"
2001-DEC-4/12:00:31	2003-317/12:00:31	43243167	0	RF_SW_TO_SW_SEL "SW2_TO_SW4"
2001-DEC-4/12:00:31	2003-317/12:00:31	43243167	0	RF_SW4_SEL_ANT "FLGA"
2001-DEC-4/12:00:31	2003-317/12:00:31	43243167	0	I1_RF_EXCITER "ON"
2001-DEC-4/12:00:32	2003-317/12:00:32	43243168	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-4/12:00:32	2003-317/12:00:32	43243168	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-4/12:00:32	2003-317/12:00:32	43243168	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-4/12:00:32	2003-317/12:00:32	43243168	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-4/12:00:33	2003-317/12:00:33	43243169	1	EXECUTE_MACRO "OBB_SIDE_1_HGA_FLGA_B"
2001-DEC-4/12:00:33	2003-317/12:00:33	43243169	0	MACRO_END
2001-DEC-4/12:00:33	2003-317/12:00:33	43243169	0	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA_B",0,598
2001-DEC-4/12:00:33	2003-317/12:00:33	43243169	0	CD_DL_RATE_SEL "51.1KHZ"
2001-DEC-4/12:00:33	2003-317/12:00:33	43243169	0	CD_DL_SUBC_MOD_ST_SEL "OFF"
2001-DEC-4/12:00:33	2003-317/12:00:33	43243169	0	CD_DL_MOD_INDX_SEL "HIGH"
2001-DEC-4/12:00:33	2003-317/12:00:33	43243169	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-4/12:00:34	2003-317/12:00:34	43243170	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-4/12:00:35	2003-317/12:00:35	43243171	1	CD_DL_SRC_SEL "RT"
2001-DEC-4/12:00:36	2003-317/12:00:36	43243172	1	RF_TWT_1_PWR "ON"
2001-DEC-4/12:00:37	2003-317/12:00:37	43243173	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-4/12:04:38	2003-317/12:04:38	43243414	241	RF_BEAM_1 "ON"
2001-DEC-4/12:04:38	2003-317/12:04:38	43243414	0	MACRO_END
2001-DEC-4/12:04:39	2003-317/12:04:39	43243415	1	MACRO_START "CDH","OBB_HI_TLM_RATES_1",0,603
2001-DEC-4/12:04:39	2003-317/12:04:39	43243415	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/12:04:39	2003-317/12:04:39	43243415	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/12:04:39	2003-317/12:04:39	43243415	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/12:04:39	2003-317/12:04:39	43243415	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4

Mission Sim 1 Timeline

2001-DEC-4/13:07:22	2003-317/13:07:22	43247178	1	NGI_NO_OP 1,105
2001-DEC-4/13:07:26	2003-317/13:07:26	43247182	4	NGI_PATCH_31 9331,0,2,31,0,81,69,81,70,81,16,81,57,81,58,81,59,81,60,81,33,81,34,81,1,81,2,81,17,81,
2001-DEC-4/13:07:31	2003-317/13:07:31	43247187	5	NGI_PATCH_31 9362,0,2,31,0,63,81,64,81,65,81,66,81,67,81,68,81,16,81,69,81,70,81,71,81,72,81,73,81,
2001-DEC-4/13:07:36	2003-317/13:07:36	43247192	5	NGI_PATCH_31 9393,0,2,31,0,81,77,81,78,81,79,81,80,81,82,81,83,81,69,81,70,81,49,81,50,81,84,81,85,
2001-DEC-4/13:07:36	2003-317/13:07:36	43247192	0	NGI_PATCH_8 9424,0,2,8,0,88,81,89,81,90,81,91,81
2001-DEC-4/14:04:59	2003-317/14:04:59	43250635	3443	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-4/14:05:04	2003-317/14:05:04	43250640	5	CD_DL_SRC_SEL "RT"
2001-DEC-4/14:05:04	2003-317/14:05:04	43250640	0	SSR_PBACK "NUM_BLOCK",0,1
2001-DEC-4/14:20:29	2003-317/14:20:29	43251565	925	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN",0,593
2001-DEC-4/14:20:29	2003-317/14:20:29	43251565	0	RF_BEAM_2 "OFF"
2001-DEC-4/14:20:29	2003-317/14:20:29	43251565	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-4/14:20:29	2003-317/14:20:29	43251565	0	RF_TWT_2_PWR "OFF"
2001-DEC-4/14:20:30	2003-317/14:20:30	43251566	1	RF_BEAM_1 "OFF"
2001-DEC-4/14:20:31	2003-317/14:20:31	43251567	1	RF_SW_TO_SW_SEL "SW1_TO_SW3"
2001-DEC-4/14:20:31	2003-317/14:20:31	43251567	0	RF_SW3_SEL_ANT "FLGA"
2001-DEC-4/14:20:31	2003-317/14:20:31	43251567	0	RF_SW2_SEL_ANT "PANCAKE"
2001-DEC-4/14:20:31	2003-317/14:20:31	43251567	0	I1_RF_EXCITER "ON"
2001-DEC-4/14:20:32	2003-317/14:20:32	43251568	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-4/14:20:32	2003-317/14:20:32	43251568	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-4/14:20:32	2003-317/14:20:32	43251568	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-4/14:20:32	2003-317/14:20:32	43251568	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-4/14:20:33	2003-317/14:20:33	43251569	1	EXECUTE_MACRO "OBB_SIDE_1_FLGA_PAN_B"
2001-DEC-4/14:20:33	2003-317/14:20:33	43251569	0	MACRO_END
2001-DEC-4/14:20:33	2003-317/14:20:33	43251569	0	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN_B",0,594
2001-DEC-4/14:20:33	2003-317/14:20:33	43251569	0	CD_DL_RATE_SEL "12.5HZ"
2001-DEC-4/14:20:33	2003-317/14:20:33	43251569	0	CD_DL_SUBC_MOD_ST_SEL "ON"
2001-DEC-4/14:20:33	2003-317/14:20:33	43251569	0	CD_DL_MOD_INDX_SEL "LOW"
2001-DEC-4/14:20:33	2003-317/14:20:33	43251569	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-4/14:20:34	2003-317/14:20:34	43251570	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-4/14:20:35	2003-317/14:20:35	43251571	1	CD_DL_SRC_SEL "RT"
2001-DEC-4/14:20:36	2003-317/14:20:36	43251572	1	RF_TWT_1_PWR "ON"
2001-DEC-4/14:20:37	2003-317/14:20:37	43251573	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-4/14:24:38	2003-317/14:24:38	43251814	241	RF_BEAM_1 "ON"
2001-DEC-4/14:24:38	2003-317/14:24:38	43251814	0	MACRO_END
2001-DEC-4/14:24:39	2003-317/14:24:39	43251815	1	MACRO_START "CDH","OBB_LO_TLM_RATES_1",0,604
2001-DEC-4/14:24:39	2003-317/14:24:39	43251815	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/14:24:39	2003-317/14:24:39	43251815	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:24:39	2003-317/14:24:39	43251815	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:24:39	2003-317/14:24:39	43251815	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:24:39	2003-317/14:24:39	43251815	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:24:40	2003-317/14:24:40	43251816	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/14:24:40	2003-317/14:24:40	43251816	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/14:24:40	2003-317/14:24:40	43251816	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:24:40	2003-317/14:24:40	43251816	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30

Mission Sim 1 Timeline

2001-DEC-4/14:24:40	2003-317/14:24:40	43251816	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:24:40	2003-317/14:24:40	43251816	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:24:40	2003-317/14:24:40	43251816	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/14:24:40	2003-317/14:24:40	43251816	0	MACRO_END
2001-DEC-4/14:44:14	2003-317/14:44:14	43252990	1174	SSR_LO_RCRD_ST "DISABLE"
2001-DEC-4/14:44:14	2003-317/14:44:14	43252990	0	SSR_WRT_PNTR_SV "LOW",2
2001-DEC-4/14:44:14	2003-317/14:44:14	43252990	0	SSR_PTR_SET "HIGH",524288
2001-DEC-4/14:44:14	2003-317/14:44:14	43252990	0	CD_INSTR_TOT_PKT_CNT 2096540,100
2001-DEC-4/14:44:14	2003-317/14:44:14	43252990	0	SSR_USG_CNT_RES 7
2001-DEC-4/14:44:15	2003-317/14:44:15	43252991	1	SSR_HI_RCRD_ST "ENABLE"
2001-DEC-4/14:44:15	2003-317/14:44:15	43252991	0	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-4/14:44:29	2003-317/14:44:29	43253005	14	MACRO_START "CDH","OBB_HI_TLM_RATES_1",0,603
2001-DEC-4/14:44:29	2003-317/14:44:29	43253005	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/14:44:29	2003-317/14:44:29	43253005	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/14:44:29	2003-317/14:44:29	43253005	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/14:44:29	2003-317/14:44:29	43253005	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-4/14:44:29	2003-317/14:44:29	43253005	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-4/14:44:30	2003-317/14:44:30	43253006	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/14:44:30	2003-317/14:44:30	43253006	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/14:44:30	2003-317/14:44:30	43253006	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/14:44:30	2003-317/14:44:30	43253006	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/14:44:30	2003-317/14:44:30	43253006	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-4/14:44:30	2003-317/14:44:30	43253006	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-4/14:44:30	2003-317/14:44:30	43253006	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/14:44:30	2003-317/14:44:30	43253006	0	MACRO_END
2001-DEC-4/14:44:59	2003-317/14:44:59	43253035	29	GC_ADD_TLM 1,256
2001-DEC-4/14:44:59	2003-317/14:44:59	43253035	0	GC_RTW_UP_PARM_LPB18_DEF 0.00000000000000,3.00000000000000,0.00000000000000,0.00000000
2001-DEC-4/14:45:00	2003-317/14:45:00	43253036	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/14:45:00	2003-317/14:45:00	43253036	0	GC_RTW_UP_PARM_LPB18_DEF 0.00000000000000,3.00000000000000,0.00000000000000,0.00000000
2001-DEC-4/14:45:01	2003-317/14:45:01	43253037	1	USE_PRIMARY_SS "GNC"
2001-DEC-4/14:45:04	2003-317/14:45:04	43253040	3	CD_GC_SCEN_SEL 11
2001-DEC-4/14:45:05	2003-317/14:45:05	43253041	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-4/14:45:20	2003-317/14:45:20	43253056	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-4/14:49:59	2003-317/14:49:59	43253335	279	GC_ADD_TLM 0,0
2001-DEC-4/14:50:00	2003-317/14:50:00	43253336	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-4/14:50:00	2003-317/14:50:00	43253336	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,2
2001-DEC-4/14:50:01	2003-317/14:50:01	43253337	1	GC_RTW_UP_PARM_LPB26_DEF 0.00000000000000,0.00000000000000,0.00000000000000
2001-DEC-4/14:50:02	2003-317/14:50:02	43253338	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/14:50:02	2003-317/14:50:02	43253338	0	GC_RTW_UP_PARM_LPB26_DEF 0.00000000000000,0.00000000000000,0.00000000000000
2001-DEC-4/14:50:02	2003-317/14:50:02	43253338	0	USE_PRIMARY_SS "GNC"
2001-DEC-4/14:50:02	2003-317/14:50:02	43253338	0	MACRO_END
2001-DEC-4/14:50:09	2003-317/14:50:09	43253345	7	GC_ADD_TLM 3,265
2001-DEC-4/14:50:24	2003-317/14:50:24	43253360	15	CFI_FLT_MOVE 10,"EXECUTE"
2001-DEC-4/14:50:28	2003-317/14:50:28	43253364	4	CFI_IMG_COMP_MODE "DISABLE","EXECUTE"

Mission Sim 1 Timeline

2001-DEC-4/14:50:28	2003-317/14:50:28	43253364	0	CFI_IMG_FORMAT "512_512_WINDOW","EXECUTE"
2001-DEC-4/14:50:28	2003-317/14:50:28	43253364	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-4/14:50:29	2003-317/14:50:29	43253365	1	CFI_IMG_EXP 100,0,"EXECUTE"
2001-DEC-4/14:50:29	2003-317/14:50:29	43253365	0	CFI_IMG_IMAGE 28,3,"EXECUTE"
2001-DEC-4/14:51:59	2003-317/14:51:59	43253455	90	SSR_HI_RCRD_ST "DISABLE"
2001-DEC-4/14:51:59	2003-317/14:51:59	43253455	0	SSR_WRT_PNTR_SV "HIGH",3
2001-DEC-4/14:51:59	2003-317/14:51:59	43253455	0	SSR_PTR_SET "LOW",786432
2001-DEC-4/14:51:59	2003-317/14:51:59	43253455	0	SSR_LO_RCRD_CTL "CONT",0
2001-DEC-4/14:52:00	2003-317/14:52:00	43253456	1	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-4/14:52:44	2003-317/14:52:44	43253500	44	GC_ADD_TLM 0,0
2001-DEC-4/14:52:59	2003-317/14:52:59	43253515	15	MACRO_START "CDH","OBB_LO_TLM_RATES_1",0,604
2001-DEC-4/14:52:59	2003-317/14:52:59	43253515	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/14:52:59	2003-317/14:52:59	43253515	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:52:59	2003-317/14:52:59	43253515	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:52:59	2003-317/14:52:59	43253515	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:52:59	2003-317/14:52:59	43253515	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:53:00	2003-317/14:53:00	43253516	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/14:53:00	2003-317/14:53:00	43253516	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/14:53:00	2003-317/14:53:00	43253516	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:53:00	2003-317/14:53:00	43253516	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:53:00	2003-317/14:53:00	43253516	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:53:00	2003-317/14:53:00	43253516	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/14:53:00	2003-317/14:53:00	43253516	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/14:53:00	2003-317/14:53:00	43253516	0	MACRO_END
2001-DEC-4/15:38:59	2003-317/15:38:59	43256275	2759	GC_ADD_TLM 1,256
2001-DEC-4/15:38:59	2003-317/15:38:59	43256275	0	CD_GC_SCEN_SEL 3
2001-DEC-4/15:39:00	2003-317/15:39:00	43256276	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-4/15:39:15	2003-317/15:39:15	43256291	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-4/15:43:59	2003-317/15:43:59	43256575	284	GC_ADD_TLM 0,0
2001-DEC-4/15:44:00	2003-317/15:44:00	43256576	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-4/15:44:00	2003-317/15:44:00	43256576	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-4/15:44:01	2003-317/15:44:01	43256577	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-4/15:44:02	2003-317/15:44:02	43256578	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/15:44:02	2003-317/15:44:02	43256578	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-4/15:44:02	2003-317/15:44:02	43256578	0	USE_PRIMARY_SS "GNC"
2001-DEC-4/15:44:02	2003-317/15:44:02	43256578	0	MACRO_END
2001-DEC-4/15:45:29	2003-317/15:45:29	43256665	87	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA",0,597
2001-DEC-4/15:45:29	2003-317/15:45:29	43256665	0	RF_BEAM_2 "OFF"
2001-DEC-4/15:45:29	2003-317/15:45:29	43256665	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-4/15:45:29	2003-317/15:45:29	43256665	0	RF_TWT_2_PWR "OFF"
2001-DEC-4/15:45:30	2003-317/15:45:30	43256666	1	RF_BEAM_1 "OFF"
2001-DEC-4/15:45:31	2003-317/15:45:31	43256667	1	RF_SW1_SEL_ANT "HGA"
2001-DEC-4/15:45:31	2003-317/15:45:31	43256667	0	RF_SW_TO_SW_SEL "SW2_TO_SW4"
2001-DEC-4/15:45:31	2003-317/15:45:31	43256667	0	RF_SW4_SEL_ANT "FLGA"

Mission Sim 1 Timeline

2001-DEC-4/15:45:31	2003-317/15:45:31	43256667	0	I1_RF_EXCITER "ON"
2001-DEC-4/15:45:32	2003-317/15:45:32	43256668	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-4/15:45:32	2003-317/15:45:32	43256668	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-4/15:45:32	2003-317/15:45:32	43256668	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-4/15:45:32	2003-317/15:45:32	43256668	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-4/15:45:33	2003-317/15:45:33	43256669	1	EXECUTE_MACRO "OBB_SIDE_1_HGA_FLGA_B"
2001-DEC-4/15:45:33	2003-317/15:45:33	43256669	0	MACRO_END
2001-DEC-4/15:45:33	2003-317/15:45:33	43256669	0	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA_B",0,598
2001-DEC-4/15:45:33	2003-317/15:45:33	43256669	0	CD_DL_RATE_SEL "51.1KHZ"
2001-DEC-4/15:45:33	2003-317/15:45:33	43256669	0	CD_DL_SUBC_MOD_ST_SEL "OFF"
2001-DEC-4/15:45:33	2003-317/15:45:33	43256669	0	CD_DL_MOD_INDX_SEL "HIGH"
2001-DEC-4/15:45:33	2003-317/15:45:33	43256669	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-4/15:45:34	2003-317/15:45:34	43256670	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-4/15:45:35	2003-317/15:45:35	43256671	1	CD_DL_SRC_SEL "RT"
2001-DEC-4/15:45:36	2003-317/15:45:36	43256672	1	RF_TWT_1_PWR "ON"
2001-DEC-4/15:45:37	2003-317/15:45:37	43256673	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-4/15:49:38	2003-317/15:49:38	43256914	241	RF_BEAM_1 "ON"
2001-DEC-4/15:49:38	2003-317/15:49:38	43256914	0	MACRO_END
2001-DEC-4/15:49:39	2003-317/15:49:39	43256915	1	MACRO_START "CDH","OBB_HI_TLM_RATES_1",0,603
2001-DEC-4/15:49:39	2003-317/15:49:39	43256915	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/15:49:39	2003-317/15:49:39	43256915	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/15:49:39	2003-317/15:49:39	43256915	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/15:49:39	2003-317/15:49:39	43256915	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-4/15:49:39	2003-317/15:49:39	43256915	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-4/15:49:40	2003-317/15:49:40	43256916	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/15:49:40	2003-317/15:49:40	43256916	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/15:49:40	2003-317/15:49:40	43256916	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/15:49:40	2003-317/15:49:40	43256916	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/15:49:40	2003-317/15:49:40	43256916	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-4/15:49:40	2003-317/15:49:40	43256916	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-4/15:49:40	2003-317/15:49:40	43256916	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/15:49:40	2003-317/15:49:40	43256916	0	MACRO_END
2001-DEC-4/16:18:59	2003-317/16:18:59	43258675	1759	SSR_LO_RCRD_ST "DISABLE"
2001-DEC-4/16:18:59	2003-317/16:18:59	43258675	0	SSR_WRT_PNTR_SV "LOW",4
2001-DEC-4/16:18:59	2003-317/16:18:59	43258675	0	SSR_PTR_SET "LOW",1048576
2001-DEC-4/16:18:59	2003-317/16:18:59	43258675	0	SSR_LO_RCRD_CTL "CONT",0
2001-DEC-4/16:19:00	2003-317/16:19:00	43258676	1	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-4/16:19:27	2003-317/16:19:27	43258703	27	CD_DL_INTRLV_SEL "THIRTYTWO"
2001-DEC-4/16:19:27	2003-317/16:19:27	43258703	0	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-4/16:19:27	2003-317/16:19:27	43258703	0	AUT_RUL_LOAD 403,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",30,30,"VALUE","EQUALS","UNSIGN"
2001-DEC-4/16:19:27	2003-317/16:19:27	43258703	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_3"
2001-DEC-4/16:19:27	2003-317/16:19:27	43258703	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",403,403
2001-DEC-4/16:19:28	2003-317/16:19:28	43258704	1	AUT_RUL_LOAD 402,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",40,40,"VALUE","EQUALS","UNSIGN"
2001-DEC-4/16:19:28	2003-317/16:19:28	43258704	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_2"

Mission Sim 1 Timeline

2001-DEC-4/16:19:28	2003-317/16:19:28	43258704	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",402,402
2001-DEC-4/16:19:29	2003-317/16:19:29	43258705	1	AUT_RUL_LOAD 404,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",50,50,"VALUE","EQUALS","UNSIGN
2001-DEC-4/16:19:29	2003-317/16:19:29	43258705	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_4"
2001-DEC-4/16:19:29	2003-317/16:19:29	43258705	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",404,404
2001-DEC-4/18:19:59	2003-317/18:19:59	43265935	7230	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-4/18:20:04	2003-317/18:20:04	43265940	5	CD_DL_SRC_SEL "RT"
2001-DEC-4/18:20:04	2003-317/18:20:04	43265940	0	SSR_PBACK "NUM_BLOCK",0,1
2001-DEC-4/18:35:29	2003-317/18:35:29	43266865	925	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN",0,593
2001-DEC-4/18:35:29	2003-317/18:35:29	43266865	0	RF_BEAM_2 "OFF"
2001-DEC-4/18:35:29	2003-317/18:35:29	43266865	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-4/18:35:29	2003-317/18:35:29	43266865	0	RF_TWT_2_PWR "OFF"
2001-DEC-4/18:35:30	2003-317/18:35:30	43266866	1	RF_BEAM_1 "OFF"
2001-DEC-4/18:35:31	2003-317/18:35:31	43266867	1	RF_SW_TO_SW_SEL "SW1_TO_SW3"
2001-DEC-4/18:35:31	2003-317/18:35:31	43266867	0	RF_SW3_SEL_ANT "FLGA"
2001-DEC-4/18:35:31	2003-317/18:35:31	43266867	0	RF_SW2_SEL_ANT "PANCAKE"
2001-DEC-4/18:35:31	2003-317/18:35:31	43266867	0	I1_RF_EXCITER "ON"
2001-DEC-4/18:35:32	2003-317/18:35:32	43266868	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-4/18:35:32	2003-317/18:35:32	43266868	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-4/18:35:32	2003-317/18:35:32	43266868	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-4/18:35:32	2003-317/18:35:32	43266868	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-4/18:35:33	2003-317/18:35:33	43266869	1	EXECUTE_MACRO "OBB_SIDE_1_FLGA_PAN_B"
2001-DEC-4/18:35:33	2003-317/18:35:33	43266869	0	MACRO_END
2001-DEC-4/18:35:33	2003-317/18:35:33	43266869	0	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN_B",0,594
2001-DEC-4/18:35:33	2003-317/18:35:33	43266869	0	CD_DL_RATE_SEL "12.5HZ"
2001-DEC-4/18:35:33	2003-317/18:35:33	43266869	0	CD_DL_SUBC_MOD_ST_SEL "ON"
2001-DEC-4/18:35:33	2003-317/18:35:33	43266869	0	CD_DL_MOD_INDX_SEL "LOW"
2001-DEC-4/18:35:33	2003-317/18:35:33	43266869	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-4/18:35:34	2003-317/18:35:34	43266870	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-4/18:35:35	2003-317/18:35:35	43266871	1	CD_DL_SRC_SEL "RT"
2001-DEC-4/18:35:36	2003-317/18:35:36	43266872	1	RF_TWT_1_PWR "ON"
2001-DEC-4/18:35:37	2003-317/18:35:37	43266873	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-4/18:39:38	2003-317/18:39:38	43267114	241	RF_BEAM_1 "ON"
2001-DEC-4/18:39:38	2003-317/18:39:38	43267114	0	MACRO_END
2001-DEC-4/18:39:39	2003-317/18:39:39	43267115	1	MACRO_START "CDH","OBB_LO_TLM_RATES_1",0,604
2001-DEC-4/18:39:39	2003-317/18:39:39	43267115	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/18:39:39	2003-317/18:39:39	43267115	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/18:39:39	2003-317/18:39:39	43267115	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/18:39:39	2003-317/18:39:39	43267115	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/18:39:39	2003-317/18:39:39	43267115	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/18:39:40	2003-317/18:39:40	43267116	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/18:39:40	2003-317/18:39:40	43267116	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/18:39:40	2003-317/18:39:40	43267116	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/18:39:40	2003-317/18:39:40	43267116	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/18:39:40	2003-317/18:39:40	43267116	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30

Mission Sim 1 Timeline

2001-DEC-4/18:39:40	2003-317/18:39:40	43267116	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/18:39:40	2003-317/18:39:40	43267116	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/18:39:40	2003-317/18:39:40	43267116	0	MACRO_END
2001-DEC-4/18:59:14	2003-317/18:59:14	43268290	1174	SSR_LO_RCRD_ST "DISABLE"
2001-DEC-4/18:59:14	2003-317/18:59:14	43268290	0	SSR_WRT_PNTR_SV "LOW",5
2001-DEC-4/18:59:14	2003-317/18:59:14	43268290	0	SSR_PTR_SET "HIGH",1311232
2001-DEC-4/18:59:14	2003-317/18:59:14	43268290	0	CD_INSTR_TOT_PKT_CNT 1309596,100
2001-DEC-4/18:59:14	2003-317/18:59:14	43268290	0	SSR_USG_CNT_RES 7
2001-DEC-4/18:59:15	2003-317/18:59:15	43268291	1	SSR_HI_RCRD_ST "ENABLE"
2001-DEC-4/18:59:15	2003-317/18:59:15	43268291	0	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-4/18:59:29	2003-317/18:59:29	43268305	14	MACRO_START "CDH","OBB_HI_TLM_RATES_1",0,603
2001-DEC-4/18:59:29	2003-317/18:59:29	43268305	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/18:59:29	2003-317/18:59:29	43268305	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/18:59:29	2003-317/18:59:29	43268305	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/18:59:29	2003-317/18:59:29	43268305	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-4/18:59:29	2003-317/18:59:29	43268305	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-4/18:59:30	2003-317/18:59:30	43268306	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/18:59:30	2003-317/18:59:30	43268306	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/18:59:30	2003-317/18:59:30	43268306	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/18:59:30	2003-317/18:59:30	43268306	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/18:59:30	2003-317/18:59:30	43268306	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-4/18:59:30	2003-317/18:59:30	43268306	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-4/18:59:30	2003-317/18:59:30	43268306	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/18:59:30	2003-317/18:59:30	43268306	0	MACRO_END
2001-DEC-4/18:59:59	2003-317/18:59:59	43268335	29	GC_ADD_TLM 1,256
2001-DEC-4/18:59:59	2003-317/18:59:59	43268335	0	GC_RTW_UP_PARM_LPB18_DEF 0.00000000000000,3.00000000000000,0.00000000000000,0.00000000
2001-DEC-4/19:00:00	2003-317/19:00:00	43268336	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/19:00:00	2003-317/19:00:00	43268336	0	GC_RTW_UP_PARM_LPB18_DEF 0.00000000000000,3.00000000000000,0.00000000000000,0.00000000
2001-DEC-4/19:00:01	2003-317/19:00:01	43268337	1	USE_PRIMARY_SS "GNC"
2001-DEC-4/19:00:04	2003-317/19:00:04	43268340	3	CD_GC_SCEN_SEL 11
2001-DEC-4/19:00:05	2003-317/19:00:05	43268341	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-4/19:00:20	2003-317/19:00:20	43268356	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-4/19:04:59	2003-317/19:04:59	43268635	279	GC_ADD_TLM 0,0
2001-DEC-4/19:05:00	2003-317/19:05:00	43268636	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-4/19:05:00	2003-317/19:05:00	43268636	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,2
2001-DEC-4/19:05:01	2003-317/19:05:01	43268637	1	GC_RTW_UP_PARM_LPB26_DEF 0.00000000000000,0.00000000000000,0.00000000000000
2001-DEC-4/19:05:02	2003-317/19:05:02	43268638	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/19:05:02	2003-317/19:05:02	43268638	0	GC_RTW_UP_PARM_LPB26_DEF 0.00000000000000,0.00000000000000,0.00000000000000
2001-DEC-4/19:05:02	2003-317/19:05:02	43268638	0	USE_PRIMARY_SS "GNC"
2001-DEC-4/19:05:02	2003-317/19:05:02	43268638	0	MACRO_END
2001-DEC-4/19:05:09	2003-317/19:05:09	43268645	7	GC_ADD_TLM 3,265
2001-DEC-4/19:05:24	2003-317/19:05:24	43268660	15	CFI_FLT_MOVE 10,"EXECUTE"
2001-DEC-4/19:05:28	2003-317/19:05:28	43268664	4	CFI_IMG_COMP_MODE "DISABLE","EXECUTE"
2001-DEC-4/19:05:28	2003-317/19:05:28	43268664	0	CFI_IMG_FORMAT "512_512_WINDOW","EXECUTE"

Mission Sim 1 Timeline

2001-DEC-4/19:05:28	2003-317/19:05:28	43268664	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-4/19:05:29	2003-317/19:05:29	43268665	1	CFI_IMG_EXP 100,0,"EXECUTE"
2001-DEC-4/19:05:29	2003-317/19:05:29	43268665	0	CFI_IMG_IMAGE 28,3,"EXECUTE"
2001-DEC-4/19:06:59	2003-317/19:06:59	43268755	90	SSR_HI_RCRD_ST "DISABLE"
2001-DEC-4/19:06:59	2003-317/19:06:59	43268755	0	SSR_WRT_PNTR_SV "HIGH",6
2001-DEC-4/19:06:59	2003-317/19:06:59	43268755	0	SSR_PTR_SET "LOW",1573376
2001-DEC-4/19:06:59	2003-317/19:06:59	43268755	0	SSR_LO_RCRD_CTL "CONT",0
2001-DEC-4/19:07:00	2003-317/19:07:00	43268756	1	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-4/19:07:44	2003-317/19:07:44	43268800	44	GC_ADD_TLM 0,0
2001-DEC-4/19:07:59	2003-317/19:07:59	43268815	15	MACRO_START "CDH","OBB_LO_TLM_RATES_1",0,604
2001-DEC-4/19:07:59	2003-317/19:07:59	43268815	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/19:07:59	2003-317/19:07:59	43268815	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/19:07:59	2003-317/19:07:59	43268815	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/19:07:59	2003-317/19:07:59	43268815	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/19:07:59	2003-317/19:07:59	43268815	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/19:08:00	2003-317/19:08:00	43268816	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/19:08:00	2003-317/19:08:00	43268816	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/19:08:00	2003-317/19:08:00	43268816	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/19:08:00	2003-317/19:08:00	43268816	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/19:08:00	2003-317/19:08:00	43268816	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/19:08:00	2003-317/19:08:00	43268816	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/19:08:00	2003-317/19:08:00	43268816	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/19:08:00	2003-317/19:08:00	43268816	0	MACRO_END
2001-DEC-4/19:29:37	2003-317/19:29:37	43270113	1297	SSR_LO_RCRD_ST "DISABLE"
2001-DEC-4/19:29:37	2003-317/19:29:37	43270113	0	SSR_WRT_PNTR_SV "LOW",7
2001-DEC-4/19:29:37	2003-317/19:29:37	43270113	0	SSR_PTR_SET "HIGH",1835520
2001-DEC-4/19:29:37	2003-317/19:29:37	43270113	0	CD_INSTR_TOT_PKT_CNT 785308,100
2001-DEC-4/19:29:37	2003-317/19:29:37	43270113	0	SSR_USG_CNT_RES 7
2001-DEC-4/19:29:38	2003-317/19:29:38	43270114	1	SSR_HI_RCRD_ST "ENABLE"
2001-DEC-4/19:29:38	2003-317/19:29:38	43270114	0	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-4/19:29:59	2003-317/19:29:59	43270135	21	GC_ADD_TLM 1,256
2001-DEC-4/19:29:59	2003-317/19:29:59	43270135	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-4/19:30:00	2003-317/19:30:00	43270136	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/19:30:00	2003-317/19:30:00	43270136	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-4/19:30:01	2003-317/19:30:01	43270137	1	USE_PRIMARY_SS "GNC"
2001-DEC-4/19:30:04	2003-317/19:30:04	43270140	3	CD_GC_SCEN_SEL 5
2001-DEC-4/19:30:05	2003-317/19:30:05	43270141	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-4/19:30:20	2003-317/19:30:20	43270156	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-4/19:30:24	2003-317/19:30:24	43270160	4	GC_ADD_TLM 0,0
2001-DEC-4/19:30:25	2003-317/19:30:25	43270161	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-4/19:30:25	2003-317/19:30:25	43270161	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,2
2001-DEC-4/19:30:26	2003-317/19:30:26	43270162	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-4/19:30:27	2003-317/19:30:27	43270163	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/19:30:27	2003-317/19:30:27	43270163	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000

Mission Sim 1 Timeline

2001-DEC-4/19:30:27	2003-317/19:30:27	43270163	0	USE_PRIMARY_SS "GNC"
2001-DEC-4/19:30:27	2003-317/19:30:27	43270163	0	MACRO_END
2001-DEC-4/19:30:33	2003-317/19:30:33	43270169	6	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-4/19:30:37	2003-317/19:30:37	43270173	4	CFI_IMG_COMP_ALG "ROOT_2","EXECUTE"
2001-DEC-4/19:30:37	2003-317/19:30:37	43270173	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-4/19:30:37	2003-317/19:30:37	43270173	0	CFI_IMG_FORMAT "512 512_REBIN","EXECUTE"
2001-DEC-4/19:30:37	2003-317/19:30:37	43270173	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-4/19:30:38	2003-317/19:30:38	43270174	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-4/19:30:38	2003-317/19:30:38	43270174	0	CFI_IMG_IMAGE 29,7,"EXECUTE"
2001-DEC-4/19:30:39	2003-317/19:30:39	43270175	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-4/19:30:46	2003-317/19:30:46	43270182	7	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-4/19:30:53	2003-317/19:30:53	43270189	7	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-4/19:31:00	2003-317/19:31:00	43270196	7	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-4/19:31:18	2003-317/19:31:18	43270214	18	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-4/19:31:22	2003-317/19:31:22	43270218	4	CFI_IMG_COMP_ALG "LINEARR","EXECUTE"
2001-DEC-4/19:31:22	2003-317/19:31:22	43270218	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-4/19:31:22	2003-317/19:31:22	43270218	0	CFI_IMG_FORMAT "256 256_REBIN","EXECUTE"
2001-DEC-4/19:31:22	2003-317/19:31:22	43270218	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-4/19:31:23	2003-317/19:31:23	43270219	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-4/19:31:23	2003-317/19:31:23	43270219	0	CFI_IMG_IMAGE 10,9,"EXECUTE"
2001-DEC-4/19:31:24	2003-317/19:31:24	43270220	1	CFI_FLT_MOVE 9,"EXECUTE"
2001-DEC-4/19:31:49	2003-317/19:31:49	43270245	25	GC_ADD_TLM 1,256
2001-DEC-4/19:31:49	2003-317/19:31:49	43270245	0	CD_GC_SCEN_SEL 4
2001-DEC-4/19:31:50	2003-317/19:31:50	43270246	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-4/19:32:05	2003-317/19:32:05	43270261	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-4/19:36:49	2003-317/19:36:49	43270545	284	GC_ADD_TLM 0,0
2001-DEC-4/19:36:50	2003-317/19:36:50	43270546	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-4/19:36:50	2003-317/19:36:50	43270546	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-4/19:36:51	2003-317/19:36:51	43270547	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-4/19:36:52	2003-317/19:36:52	43270548	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/19:36:52	2003-317/19:36:52	43270548	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-4/19:36:52	2003-317/19:36:52	43270548	0	USE_PRIMARY_SS "GNC"
2001-DEC-4/19:36:52	2003-317/19:36:52	43270548	0	MACRO_END
2001-DEC-4/19:53:59	2003-317/19:53:59	43271575	1027	GC_ADD_TLM 1,256
2001-DEC-4/19:53:59	2003-317/19:53:59	43271575	0	CD_GC_SCEN_SEL 3
2001-DEC-4/19:54:00	2003-317/19:54:00	43271576	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-4/19:54:15	2003-317/19:54:15	43271591	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-4/19:58:59	2003-317/19:58:59	43271875	284	GC_ADD_TLM 0,0
2001-DEC-4/19:59:00	2003-317/19:59:00	43271876	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-4/19:59:00	2003-317/19:59:00	43271876	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-4/19:59:01	2003-317/19:59:01	43271877	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-4/19:59:02	2003-317/19:59:02	43271878	1	USE_REDUNDANT_SS "GNC"
2001-DEC-4/19:59:02	2003-317/19:59:02	43271878	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-4/19:59:02	2003-317/19:59:02	43271878	0	USE_PRIMARY_SS "GNC"

Mission Sim 1 Timeline

2001-DEC-4/19:59:02	2003-317/19:59:02	43271878	0	MACRO_END
2001-DEC-4/20:00:29	2003-317/20:00:29	43271965	87	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA",0,597
2001-DEC-4/20:00:29	2003-317/20:00:29	43271965	0	RF_BEAM_2 "OFF"
2001-DEC-4/20:00:29	2003-317/20:00:29	43271965	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-4/20:00:29	2003-317/20:00:29	43271965	0	RF_TWT_2_PWR "OFF"
2001-DEC-4/20:00:30	2003-317/20:00:30	43271966	1	RF_BEAM_1 "OFF"
2001-DEC-4/20:00:31	2003-317/20:00:31	43271967	1	RF_SW1_SEL_ANT "HGA"
2001-DEC-4/20:00:31	2003-317/20:00:31	43271967	0	RF_SW_TO_SW_SEL "SW2_TO_SW4"
2001-DEC-4/20:00:31	2003-317/20:00:31	43271967	0	RF_SW4_SEL_ANT "FLGA"
2001-DEC-4/20:00:31	2003-317/20:00:31	43271967	0	I1_RF_EXCITER "ON"
2001-DEC-4/20:00:32	2003-317/20:00:32	43271968	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-4/20:00:32	2003-317/20:00:32	43271968	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-4/20:00:32	2003-317/20:00:32	43271968	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-4/20:00:32	2003-317/20:00:32	43271968	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-4/20:00:33	2003-317/20:00:33	43271969	1	EXECUTE_MACRO "OBB_SIDE_1_HGA_FLGA_B"
2001-DEC-4/20:00:33	2003-317/20:00:33	43271969	0	MACRO_END
2001-DEC-4/20:00:33	2003-317/20:00:33	43271969	0	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA_B",0,598
2001-DEC-4/20:00:33	2003-317/20:00:33	43271969	0	CD_DL_RATE_SEL "51.1KHZ"
2001-DEC-4/20:00:33	2003-317/20:00:33	43271969	0	CD_DL_SUBC_MOD_ST_SEL "OFF"
2001-DEC-4/20:00:33	2003-317/20:00:33	43271969	0	CD_DL_MOD_IND_X_SEL "HIGH"
2001-DEC-4/20:00:33	2003-317/20:00:33	43271969	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-4/20:00:34	2003-317/20:00:34	43271970	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-4/20:00:35	2003-317/20:00:35	43271971	1	CD_DL_SRC_SEL "RT"
2001-DEC-4/20:00:36	2003-317/20:00:36	43271972	1	RF_TWT_1_PWR "ON"
2001-DEC-4/20:00:37	2003-317/20:00:37	43271973	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-4/20:04:38	2003-317/20:04:38	43272214	241	RF_BEAM_1 "ON"
2001-DEC-4/20:04:38	2003-317/20:04:38	43272214	0	MACRO_END
2001-DEC-4/20:04:39	2003-317/20:04:39	43272215	1	MACRO_START "CDH","OBB_HI_TLM_RATES_1",0,603
2001-DEC-4/20:04:39	2003-317/20:04:39	43272215	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/20:04:39	2003-317/20:04:39	43272215	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/20:04:39	2003-317/20:04:39	43272215	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/20:04:39	2003-317/20:04:39	43272215	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-4/20:04:39	2003-317/20:04:39	43272215	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-4/20:04:40	2003-317/20:04:40	43272216	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/20:04:40	2003-317/20:04:40	43272216	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-4/20:04:40	2003-317/20:04:40	43272216	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-4/20:04:40	2003-317/20:04:40	43272216	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-4/20:04:40	2003-317/20:04:40	43272216	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-4/20:04:40	2003-317/20:04:40	43272216	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-4/20:04:40	2003-317/20:04:40	43272216	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/20:04:40	2003-317/20:04:40	43272216	0	MACRO_END
2001-DEC-4/20:33:59	2003-317/20:33:59	43273975	1759	SSR_HI_RCRD_ST "DISABLE"
2001-DEC-4/20:33:59	2003-317/20:33:59	43273975	0	SSR_WRT_PNTR_SV "HIGH",8
2001-DEC-4/20:33:59	2003-317/20:33:59	43273975	0	SSR_PTR_SET "LOW",262144

Mission Sim 1 Timeline

2001-DEC-4/20:33:59	2003-317/20:33:59	43273975	0	SSR_LO_RCRD_CTL "CONT",0
2001-DEC-4/20:34:00	2003-317/20:34:00	43273976	1	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-4/20:34:27	2003-317/20:34:27	43274003	27	CD_DL_INTRLV_SEL "THIRTYTWO"
2001-DEC-4/20:34:27	2003-317/20:34:27	43274003	0	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-4/20:34:27	2003-317/20:34:27	43274003	0	AUT_RUL_LOAD 406,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",30,30,"VALUE","EQUALS","UNSIGN"
2001-DEC-4/20:34:27	2003-317/20:34:27	43274003	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_6"
2001-DEC-4/20:34:27	2003-317/20:34:27	43274003	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",406,406
2001-DEC-4/20:34:28	2003-317/20:34:28	43274004	1	AUT_RUL_LOAD 405,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",40,40,"VALUE","EQUALS","UNSIGN"
2001-DEC-4/20:34:28	2003-317/20:34:28	43274004	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_5"
2001-DEC-4/20:34:28	2003-317/20:34:28	43274004	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",405,405
2001-DEC-4/20:34:29	2003-317/20:34:29	43274005	1	AUT_RUL_LOAD 407,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",50,50,"VALUE","EQUALS","UNSIGN"
2001-DEC-4/20:34:29	2003-317/20:34:29	43274005	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_7"
2001-DEC-4/20:34:29	2003-317/20:34:29	43274005	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",407,407
2001-DEC-4/20:34:30	2003-317/20:34:30	43274006	1	AUT_RUL_LOAD 408,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",60,60,"VALUE","EQUALS","UNSIGN"
2001-DEC-4/20:34:30	2003-317/20:34:30	43274006	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_8"
2001-DEC-4/20:34:30	2003-317/20:34:30	43274006	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",408,408
2001-DEC-4/22:34:59	2003-317/22:34:59	43281235	7229	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-4/22:35:04	2003-317/22:35:04	43281240	5	CD_DL_SRC_SEL "RT"
2001-DEC-4/22:35:04	2003-317/22:35:04	43281240	0	SSR_PBACK "NUM_BLOCK",0,1
2001-DEC-4/22:50:29	2003-317/22:50:29	43282165	925	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN",0,593
2001-DEC-4/22:50:29	2003-317/22:50:29	43282165	0	RF_BEAM_2 "OFF"
2001-DEC-4/22:50:29	2003-317/22:50:29	43282165	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-4/22:50:29	2003-317/22:50:29	43282165	0	RF_TWT_2_PWR "OFF"
2001-DEC-4/22:50:30	2003-317/22:50:30	43282166	1	RF_BEAM_1 "OFF"
2001-DEC-4/22:50:31	2003-317/22:50:31	43282167	1	RF_SW_TO_SW_SEL "SW1_TO_SW3"
2001-DEC-4/22:50:31	2003-317/22:50:31	43282167	0	RF_SW3_SEL_ANT "FLGA"
2001-DEC-4/22:50:31	2003-317/22:50:31	43282167	0	RF_SW2_SEL_ANT "PANCAKE"
2001-DEC-4/22:50:31	2003-317/22:50:31	43282167	0	I1_RF_EXCITER "ON"
2001-DEC-4/22:50:32	2003-317/22:50:32	43282168	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-4/22:50:32	2003-317/22:50:32	43282168	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-4/22:50:32	2003-317/22:50:32	43282168	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-4/22:50:32	2003-317/22:50:32	43282168	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-4/22:50:33	2003-317/22:50:33	43282169	1	EXECUTE_MACRO "OBB_SIDE_1_FLGA_PAN_B"
2001-DEC-4/22:50:33	2003-317/22:50:33	43282169	0	MACRO_END
2001-DEC-4/22:50:33	2003-317/22:50:33	43282169	0	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN_B",0,594
2001-DEC-4/22:50:33	2003-317/22:50:33	43282169	0	CD_DL_RATE_SEL "12.5HZ"
2001-DEC-4/22:50:33	2003-317/22:50:33	43282169	0	CD_DL_SUBC_MOD_ST_SEL "ON"
2001-DEC-4/22:50:33	2003-317/22:50:33	43282169	0	CD_DL_MOD_INDX_SEL "LOW"
2001-DEC-4/22:50:33	2003-317/22:50:33	43282169	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-4/22:50:34	2003-317/22:50:34	43282170	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-4/22:50:35	2003-317/22:50:35	43282171	1	CD_DL_SRC_SEL "RT"
2001-DEC-4/22:50:36	2003-317/22:50:36	43282172	1	RF_TWT_1_PWR "ON"
2001-DEC-4/22:50:37	2003-317/22:50:37	43282173	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-4/22:54:38	2003-317/22:54:38	43282414	241	RF_BEAM_1 "ON"

Mission Sim 1 Timeline

2001-DEC-4/22:54:38	2003-317/22:54:38	43282414	0	MACRO_END
2001-DEC-4/22:54:39	2003-317/22:54:39	43282415	1	MACRO_START "CDH","OBB_LO_TLM_RATES_1",0,604
2001-DEC-4/22:54:39	2003-317/22:54:39	43282415	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/22:54:39	2003-317/22:54:39	43282415	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/22:54:39	2003-317/22:54:39	43282415	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/22:54:39	2003-317/22:54:39	43282415	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/22:54:39	2003-317/22:54:39	43282415	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/22:54:40	2003-317/22:54:40	43282416	1	USE_REDUNDANT_SS "CDH"
2001-DEC-4/22:54:40	2003-317/22:54:40	43282416	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-4/22:54:40	2003-317/22:54:40	43282416	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-4/22:54:40	2003-317/22:54:40	43282416	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-4/22:54:40	2003-317/22:54:40	43282416	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-4/22:54:40	2003-317/22:54:40	43282416	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-4/22:54:40	2003-317/22:54:40	43282416	0	USE_PRIMARY_SS "CDH"
2001-DEC-4/22:54:40	2003-317/22:54:40	43282416	0	MACRO_END
2001-DEC-5/01:59:37	2003-318/01:59:37	43293513	11097	SSR_LO_RCRD_ST "DISABLE"
2001-DEC-5/01:59:37	2003-318/01:59:37	43293513	0	SSR_WRT_PNTR_SV "LOW",2
2001-DEC-5/01:59:37	2003-318/01:59:37	43293513	0	SSR_PTR_SET "HIGH",524288
2001-DEC-5/01:59:37	2003-318/01:59:37	43293513	0	CD_INSTR_TOT_PKT_CNT 2096540,100
2001-DEC-5/01:59:37	2003-318/01:59:37	43293513	0	SSR_USG_CNT_RES 7
2001-DEC-5/01:59:38	2003-318/01:59:38	43293514	1	SSR_HI_RCRD_ST "ENABLE"
2001-DEC-5/01:59:38	2003-318/01:59:38	43293514	0	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-5/01:59:59	2003-318/01:59:59	43293535	21	GC_ADD_TLM 1,256
2001-DEC-5/01:59:59	2003-318/01:59:59	43293535	0	GC_RTW_UP_PARM_LPB12_DEF 0.00000000000000,4.00000000000000,0.00000000000000,0.00000000
2001-DEC-5/02:00:00	2003-318/02:00:00	43293536	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/02:00:00	2003-318/02:00:00	43293536	0	GC_RTW_UP_PARM_LPB12_DEF 0.00000000000000,4.00000000000000,0.00000000000000,0.00000000
2001-DEC-5/02:00:01	2003-318/02:00:01	43293537	1	USE_PRIMARY_SS "GNC"
2001-DEC-5/02:00:04	2003-318/02:00:04	43293540	3	CD_GC_SCEN_SEL 5
2001-DEC-5/02:00:05	2003-318/02:00:05	43293541	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/02:00:20	2003-318/02:00:20	43293556	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/02:00:24	2003-318/02:00:24	43293560	4	GC_ADD_TLM 0,0
2001-DEC-5/02:00:25	2003-318/02:00:25	43293561	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-5/02:00:25	2003-318/02:00:25	43293561	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,2
2001-DEC-5/02:00:26	2003-318/02:00:26	43293562	1	GC_RTW_UP_PARM_LPB26_DEF 0.00000000000000,0.00000000000000,0.00000000000000
2001-DEC-5/02:00:27	2003-318/02:00:27	43293563	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/02:00:27	2003-318/02:00:27	43293563	0	GC_RTW_UP_PARM_LPB26_DEF 0.00000000000000,0.00000000000000,0.00000000000000
2001-DEC-5/02:00:27	2003-318/02:00:27	43293563	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/02:00:27	2003-318/02:00:27	43293563	0	MACRO_END
2001-DEC-5/02:00:33	2003-318/02:00:33	43293569	6	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/02:00:37	2003-318/02:00:37	43293573	4	CFI_IMG_COMP_ALG "HIGH_RANGE","EXECUTE"
2001-DEC-5/02:00:37	2003-318/02:00:37	43293573	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/02:00:37	2003-318/02:00:37	43293573	0	CFI_IMG_FORMAT "512 512_REBIN","EXECUTE"
2001-DEC-5/02:00:37	2003-318/02:00:37	43293573	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/02:00:38	2003-318/02:00:38	43293574	1	CFI_IMG_EXP 1,5,"EXECUTE"

Mission Sim 1 Timeline

2001-DEC-5/02:00:38	2003-318/02:00:38	43293574	0	CFI_IMG_IMAGE 29,7,"EXECUTE"
2001-DEC-5/02:00:39	2003-318/02:00:39	43293575	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/02:00:46	2003-318/02:00:46	43293582	7	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/02:00:53	2003-318/02:00:53	43293589	7	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/02:01:00	2003-318/02:01:00	43293596	7	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/02:01:18	2003-318/02:01:18	43293614	18	CFI_FLT_MOVE 7,"EXECUTE"
2001-DEC-5/02:01:22	2003-318/02:01:22	43293618	4	CFI_IMG_COMP_ALG "HIGH_RANGE","EXECUTE"
2001-DEC-5/02:01:22	2003-318/02:01:22	43293618	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/02:01:22	2003-318/02:01:22	43293618	0	CFI_IMG_FORMAT "256_256_REBIN","EXECUTE"
2001-DEC-5/02:01:22	2003-318/02:01:22	43293618	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/02:01:23	2003-318/02:01:23	43293619	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/02:01:23	2003-318/02:01:23	43293619	0	CFI_IMG_IMAGE 10,9,"EXECUTE"
2001-DEC-5/02:01:24	2003-318/02:01:24	43293620	1	CFI_FLT_MOVE 10,"EXECUTE"
2001-DEC-5/02:01:49	2003-318/02:01:49	43293645	25	GC_ADD_TLM 1,256
2001-DEC-5/02:01:49	2003-318/02:01:49	43293645	0	GC_RTW_UP_PARM LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/02:01:50	2003-318/02:01:50	43293646	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/02:01:50	2003-318/02:01:50	43293646	0	GC_RTW_UP_PARM LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/02:01:51	2003-318/02:01:51	43293647	1	USE_PRIMARY_SS "GNC"
2001-DEC-5/02:01:54	2003-318/02:01:54	43293650	3	CD_GC_SCEN_SEL 5
2001-DEC-5/02:01:55	2003-318/02:01:55	43293651	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/02:02:10	2003-318/02:02:10	43293666	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/02:02:14	2003-318/02:02:14	43293670	4	GC_ADD_TLM 0,0
2001-DEC-5/02:02:23	2003-318/02:02:23	43293679	9	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/02:02:27	2003-318/02:02:27	43293683	4	CFI_IMG_COMP_ALG "HIGH_RANGE","EXECUTE"
2001-DEC-5/02:02:27	2003-318/02:02:27	43293683	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/02:02:27	2003-318/02:02:27	43293683	0	CFI_IMG_FORMAT "512_512_REBIN","EXECUTE"
2001-DEC-5/02:02:27	2003-318/02:02:27	43293683	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/02:02:28	2003-318/02:02:28	43293684	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/02:02:28	2003-318/02:02:28	43293684	0	CFI_IMG_IMAGE 29,7,"EXECUTE"
2001-DEC-5/02:02:29	2003-318/02:02:29	43293685	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/02:02:36	2003-318/02:02:36	43293692	7	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/02:02:43	2003-318/02:02:43	43293699	7	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/02:02:50	2003-318/02:02:50	43293706	7	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/02:03:08	2003-318/02:03:08	43293724	18	CFI_FLT_MOVE 7,"EXECUTE"
2001-DEC-5/02:03:12	2003-318/02:03:12	43293728	4	CFI_IMG_COMP_ALG "HIGH_RANGE","EXECUTE"
2001-DEC-5/02:03:12	2003-318/02:03:12	43293728	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/02:03:12	2003-318/02:03:12	43293728	0	CFI_IMG_FORMAT "256_256_REBIN","EXECUTE"
2001-DEC-5/02:03:12	2003-318/02:03:12	43293728	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/02:03:13	2003-318/02:03:13	43293729	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/02:03:13	2003-318/02:03:13	43293729	0	CFI_IMG_IMAGE 10,9,"EXECUTE"
2001-DEC-5/02:03:14	2003-318/02:03:14	43293730	1	CFI_FLT_MOVE 10,"EXECUTE"
2001-DEC-5/02:03:39	2003-318/02:03:39	43293755	25	GC_ADD_TLM 1,256
2001-DEC-5/02:03:39	2003-318/02:03:39	43293755	0	GC_RTW_UP_PARM LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/02:03:40	2003-318/02:03:40	43293756	1	USE_REDUNDANT_SS "GNC"

Mission Sim 1 Timeline

2001-DEC-5/02:03:40	2003-318/02:03:40	43293756	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/02:03:41	2003-318/02:03:41	43293757	1	USE_PRIMARY_SS "GNC"
2001-DEC-5/02:03:44	2003-318/02:03:44	43293760	3	CD_GC_SCEN_SEL 5
2001-DEC-5/02:03:45	2003-318/02:03:45	43293761	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/02:04:00	2003-318/02:04:00	43293776	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/02:04:04	2003-318/02:04:04	43293780	4	GC_ADD_TLM 0,0
2001-DEC-5/02:04:13	2003-318/02:04:13	43293789	9	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/02:04:17	2003-318/02:04:17	43293793	4	CFI_IMG_COMP_ALG "HIGH_RANGE","EXECUTE"
2001-DEC-5/02:04:17	2003-318/02:04:17	43293793	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/02:04:17	2003-318/02:04:17	43293793	0	CFI_IMG_FORMAT "512_512_REBIN","EXECUTE"
2001-DEC-5/02:04:17	2003-318/02:04:17	43293793	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/02:04:18	2003-318/02:04:18	43293794	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/02:04:18	2003-318/02:04:18	43293794	0	CFI_IMG_IMAGE 29,7,"EXECUTE"
2001-DEC-5/02:04:19	2003-318/02:04:19	43293795	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/02:04:26	2003-318/02:04:26	43293802	7	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/02:04:33	2003-318/02:04:33	43293809	7	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/02:04:40	2003-318/02:04:40	43293816	7	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/02:04:58	2003-318/02:04:58	43293834	18	CFI_FLT_MOVE 7,"EXECUTE"
2001-DEC-5/02:05:02	2003-318/02:05:02	43293838	4	CFI_IMG_COMP_ALG "HIGH_RANGE","EXECUTE"
2001-DEC-5/02:05:02	2003-318/02:05:02	43293838	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/02:05:02	2003-318/02:05:02	43293838	0	CFI_IMG_FORMAT "256_256_REBIN","EXECUTE"
2001-DEC-5/02:05:02	2003-318/02:05:02	43293838	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/02:05:03	2003-318/02:05:03	43293839	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/02:05:03	2003-318/02:05:03	43293839	0	CFI_IMG_IMAGE 10,9,"EXECUTE"
2001-DEC-5/02:05:04	2003-318/02:05:04	43293840	1	CFI_FLT_MOVE 10,"EXECUTE"
2001-DEC-5/02:05:29	2003-318/02:05:29	43293865	25	GC_ADD_TLM 1,256
2001-DEC-5/02:05:29	2003-318/02:05:29	43293865	0	CD_GC_SCEN_SEL 4
2001-DEC-5/02:05:30	2003-318/02:05:30	43293866	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/02:05:45	2003-318/02:05:45	43293881	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/02:10:29	2003-318/02:10:29	43294165	284	GC_ADD_TLM 0,0
2001-DEC-5/02:10:30	2003-318/02:10:30	43294166	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-5/02:10:30	2003-318/02:10:30	43294166	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-5/02:10:31	2003-318/02:10:31	43294167	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/02:10:32	2003-318/02:10:32	43294168	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/02:10:32	2003-318/02:10:32	43294168	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/02:10:32	2003-318/02:10:32	43294168	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/02:10:32	2003-318/02:10:32	43294168	0	MACRO_END
2001-DEC-5/02:59:59	2003-318/02:59:59	43297135	2967	GC_ADD_TLM 1,256
2001-DEC-5/02:59:59	2003-318/02:59:59	43297135	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/03:00:00	2003-318/03:00:00	43297136	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/03:00:00	2003-318/03:00:00	43297136	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/03:00:01	2003-318/03:00:01	43297137	1	USE_PRIMARY_SS "GNC"
2001-DEC-5/03:00:04	2003-318/03:00:04	43297140	3	CD_GC_SCEN_SEL 5
2001-DEC-5/03:00:05	2003-318/03:00:05	43297141	1	CD_FLSHSEG_ER "PARAM"

Mission Sim 1 Timeline

2001-DEC-5/03:00:20	2003-318/03:00:20	43297156	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/03:00:24	2003-318/03:00:24	43297160	4	GC_ADD_TLM 0,0
2001-DEC-5/03:00:25	2003-318/03:00:25	43297161	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-5/03:00:25	2003-318/03:00:25	43297161	0	ASC_LOAD_PARAM_TC 071 "NO_ACK",71,1,2
2001-DEC-5/03:00:26	2003-318/03:00:26	43297162	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/03:00:27	2003-318/03:00:27	43297163	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/03:00:27	2003-318/03:00:27	43297163	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/03:00:27	2003-318/03:00:27	43297163	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/03:00:27	2003-318/03:00:27	43297163	0	MACRO_END
2001-DEC-5/03:00:33	2003-318/03:00:33	43297169	6	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/03:00:37	2003-318/03:00:37	43297173	4	CFI_IMG_COMP_ALG "ROOT_2","EXECUTE"
2001-DEC-5/03:00:37	2003-318/03:00:37	43297173	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/03:00:37	2003-318/03:00:37	43297173	0	CFI_IMG_FORMAT "512_512_REBIN","EXECUTE"
2001-DEC-5/03:00:37	2003-318/03:00:37	43297173	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/03:00:38	2003-318/03:00:38	43297174	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/03:00:38	2003-318/03:00:38	43297174	0	CFI_IMG_IMAGE 64,7,"EXECUTE"
2001-DEC-5/03:00:45	2003-318/03:00:45	43297181	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/03:00:46	2003-318/03:00:46	43297182	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/03:00:52	2003-318/03:00:52	43297188	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/03:00:59	2003-318/03:00:59	43297195	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/03:01:00	2003-318/03:01:00	43297196	1	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/03:01:06	2003-318/03:01:06	43297202	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/03:01:13	2003-318/03:01:13	43297209	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/03:01:14	2003-318/03:01:14	43297210	1	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/03:01:20	2003-318/03:01:20	43297216	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/03:01:27	2003-318/03:01:27	43297223	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/03:01:28	2003-318/03:01:28	43297224	1	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/03:01:34	2003-318/03:01:34	43297230	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/03:01:41	2003-318/03:01:41	43297237	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/03:01:58	2003-318/03:01:58	43297254	17	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-5/03:02:02	2003-318/03:02:02	43297258	4	CFI_IMG_COMP_ALG "LINEARR","EXECUTE"
2001-DEC-5/03:02:02	2003-318/03:02:02	43297258	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/03:02:02	2003-318/03:02:02	43297258	0	CFI_IMG_FORMAT "256_256_REBIN","EXECUTE"
2001-DEC-5/03:02:02	2003-318/03:02:02	43297258	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/03:02:03	2003-318/03:02:03	43297259	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/03:02:03	2003-318/03:02:03	43297259	0	CFI_IMG_IMAGE 28,9,"EXECUTE"
2001-DEC-5/03:02:12	2003-318/03:02:12	43297268	9	CFI_IMG_EXP 1,2,"EXECUTE"
2001-DEC-5/03:02:13	2003-318/03:02:13	43297269	1	CFI_FLT_MOVE 9,"EXECUTE"
2001-DEC-5/03:02:21	2003-318/03:02:21	43297277	8	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/03:02:30	2003-318/03:02:30	43297286	9	CFI_IMG_EXP 1,2,"EXECUTE"
2001-DEC-5/03:02:59	2003-318/03:02:59	43297315	29	GC_ADD_TLM 1,256
2001-DEC-5/03:02:59	2003-318/03:02:59	43297315	0	CD_GC_SCEN_SEL 4
2001-DEC-5/03:03:00	2003-318/03:03:00	43297316	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/03:03:15	2003-318/03:03:15	43297331	15	CD_FLSHSEG_PRGM "PARAM"

Mission Sim 1 Timeline

2001-DEC-5/03:07:59	2003-318/03:07:59	43297615	284	GC_ADD_TLM 0,0
2001-DEC-5/03:08:00	2003-318/03:08:00	43297616	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-5/03:08:00	2003-318/03:08:00	43297616	0	ASC_LOAD_PARAM_TC 071 "NO_ACK",71,1,1
2001-DEC-5/03:08:01	2003-318/03:08:01	43297617	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/03:08:02	2003-318/03:08:02	43297618	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/03:08:02	2003-318/03:08:02	43297618	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/03:08:02	2003-318/03:08:02	43297618	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/03:08:02	2003-318/03:08:02	43297618	0	MACRO_END
2001-DEC-5/03:29:59	2003-318/03:29:59	43298935	1317	SSR_HI_RCRD_ST "DISABLE"
2001-DEC-5/03:29:59	2003-318/03:29:59	43298935	0	SSR_WRT_PNTR_SV "HIGH",3
2001-DEC-5/03:29:59	2003-318/03:29:59	43298935	0	SSR_PTR_SET "LOW",786432
2001-DEC-5/03:29:59	2003-318/03:29:59	43298935	0	SSR_LO_RCRD_CTL "CONT",0
2001-DEC-5/03:30:00	2003-318/03:30:00	43298936	1	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-5/06:56:59	2003-318/06:56:59	43311355	12419	SSR_LO_RCRD_ST "DISABLE"
2001-DEC-5/06:56:59	2003-318/06:56:59	43311355	0	SSR_WRT_PNTR_SV "LOW",4
2001-DEC-5/06:56:59	2003-318/06:56:59	43311355	0	SSR_PTR_SET "LOW",1048576
2001-DEC-5/06:56:59	2003-318/06:56:59	43311355	0	SSR_LO_RCRD_CTL "CONT",0
2001-DEC-5/06:57:00	2003-318/06:57:00	43311356	1	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-5/06:57:59	2003-318/06:57:59	43311415	59	MACRO_START "CDH","OCM1_BURN_ATTITUDE",0,-1
2001-DEC-5/06:57:59	2003-318/06:57:59	43311415	0	GC_ADD_TLM 1,262409
2001-DEC-5/06:57:59	2003-318/06:57:59	43311415	0	GC_RTW_UP_PARM_LPB17_DEF 0.000000000000000,1.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/06:58:00	2003-318/06:58:00	43311416	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/06:58:00	2003-318/06:58:00	43311416	0	GC_RTW_UP_PARM_LPB17_DEF 0.000000000000000,1.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/06:58:01	2003-318/06:58:01	43311417	1	USE_PRIMARY_SS "GNC"
2001-DEC-5/06:58:04	2003-318/06:58:04	43311420	3	CD_GC_SCEN_SEL 10
2001-DEC-5/06:58:05	2003-318/06:58:05	43311421	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/06:58:20	2003-318/06:58:20	43311436	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/06:58:20	2003-318/06:58:20	43311436	0	MACRO_END
2001-DEC-5/07:17:59	2003-318/07:17:59	43312615	1179	MACRO_START "CDH","OBB_3AXIS_ASPIN",0,987
2001-DEC-5/07:17:59	2003-318/07:17:59	43312615	0	PS_PRI_TLM_PROP "ON"
2001-DEC-5/07:18:00	2003-318/07:18:00	43312616	1	PS_SEC_TLM_PROP "ON"
2001-DEC-5/07:18:01	2003-318/07:18:01	43312617	1	PRI_DV_CAT_HTR "OFF"
2001-DEC-5/07:18:02	2003-318/07:18:02	43312618	1	SEC_DV_CAT_HTR "OFF"
2001-DEC-5/07:18:03	2003-318/07:18:03	43312619	1	PRI_AD_THRUST_HTR "ON"
2001-DEC-5/07:18:04	2003-318/07:18:04	43312620	1	PRI_BC_THRUST_HTR "ON"
2001-DEC-5/07:18:05	2003-318/07:18:05	43312621	1	SEC_AD_THRUST_HTR "ON"
2001-DEC-5/07:18:06	2003-318/07:18:06	43312622	1	SEC_BC_THRUST_HTR "ON"
2001-DEC-5/07:18:07	2003-318/07:18:07	43312623	1	PRI_LV_LINE_HTR_HI "ON"
2001-DEC-5/07:18:08	2003-318/07:18:08	43312624	1	SEC_LV_LINE_HTR_HI "ON"
2001-DEC-5/07:18:09	2003-318/07:18:09	43312625	1	PRI_LV_LINE_HTR_LO "ON"
2001-DEC-5/07:18:10	2003-318/07:18:10	43312626	1	SEC_LV_LINE_HTR_LO "ON"
2001-DEC-5/07:18:11	2003-318/07:18:11	43312627	1	PRI_TANK_HTR "ON"
2001-DEC-5/07:18:12	2003-318/07:18:12	43312628	1	SEC_TANK_HTR "ON"
2001-DEC-5/07:18:13	2003-318/07:18:13	43312629	1	PRI_SC_SV_HTR "ON"

Mission Sim 1 Timeline

2001-DEC-5/07:18:14	2003-318/07:18:14	43312630	1	SEC_SC_SV_HTR "ON"
2001-DEC-5/07:18:15	2003-318/07:18:15	43312631	1	ESS_PWR "ON"
2001-DEC-5/07:18:16	2003-318/07:18:16	43312632	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-2.094395000000000
2001-DEC-5/07:18:17	2003-318/07:18:17	43312633	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/07:18:17	2003-318/07:18:17	43312633	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-2.094395000000000
2001-DEC-5/07:18:17	2003-318/07:18:17	43312633	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/07:28:17	2003-318/07:28:17	43313233	600	PRI_SPINUP_CAT_HTR "OFF"
2001-DEC-5/07:28:18	2003-318/07:28:18	43313234	1	PRI_SPINDN_CAT_HTR "OFF"
2001-DEC-5/07:28:19	2003-318/07:28:19	43313235	1	PRI_RADIAL_CAT_HTR "OFF"
2001-DEC-5/07:28:20	2003-318/07:28:20	43313236	1	SEC_SPINUP_CAT_HTR "OFF"
2001-DEC-5/07:28:21	2003-318/07:28:21	43313237	1	SEC_SPINDN_CAT_HTR "OFF"
2001-DEC-5/07:28:22	2003-318/07:28:22	43313238	1	SEC_RADIAL_CAT_HTR "OFF"
2001-DEC-5/07:28:23	2003-318/07:28:23	43313239	1	CD_TAC_MODE "OFF"
2001-DEC-5/07:28:24	2003-318/07:28:24	43313240	1	CD_GC_MODE "SPIN"
2001-DEC-5/07:28:25	2003-318/07:28:25	43313241	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/07:28:26	2003-318/07:28:26	43313242	1	GC_MODE_BIT0_SPIN_3A "SPIN"
2001-DEC-5/07:28:26	2003-318/07:28:26	43313242	0	GC_MODE_BIT1_NM_SPEC "NORMAL"
2001-DEC-5/07:28:40	2003-318/07:28:40	43313256	14	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/07:28:55	2003-318/07:28:55	43313271	15	PRI_THRUST_LV_SEL "ENABLE"
2001-DEC-5/07:28:56	2003-318/07:28:56	43313272	1	SEC_THRUST_LV_SEL "ENABLE"
2001-DEC-5/07:28:57	2003-318/07:28:57	43313273	1	PRI_THRUST_ARM "SAFE"
2001-DEC-5/07:28:58	2003-318/07:28:58	43313274	1	SEC_THRUST_ARM "SAFE"
2001-DEC-5/07:29:03	2003-318/07:29:03	43313279	5	PRI_THRUST_LV_SEL "DISABLE"
2001-DEC-5/07:29:04	2003-318/07:29:04	43313280	1	SEC_THRUST_LV_SEL "DISABLE"
2001-DEC-5/07:29:04	2003-318/07:29:04	43313280	0	MACRO_END
2001-DEC-5/07:29:59	2003-318/07:29:59	43313335	55	PS_PRI_TLM_PROP "ON"
2001-DEC-5/07:30:09	2003-318/07:30:09	43313345	10	CD_TAC_SEL "TAC_1"
2001-DEC-5/07:30:10	2003-318/07:30:10	43313346	1	CD_TAC_MODE "OFF"
2001-DEC-5/07:30:11	2003-318/07:30:11	43313347	1	CD_GC_MODE "SPIN"
2001-DEC-5/07:30:12	2003-318/07:30:12	43313348	1	CD_TAC_MODE "DELTAV"
2001-DEC-5/07:30:12	2003-318/07:30:12	43313348	0	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/07:30:27	2003-318/07:30:27	43313363	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/07:30:39	2003-318/07:30:39	43313375	12	PRI_AD_THRUST_HTR "ON"
2001-DEC-5/07:30:40	2003-318/07:30:40	43313376	1	PRI_BC_THRUST_HTR "ON"
2001-DEC-5/07:30:41	2003-318/07:30:41	43313377	1	SEC_AD_THRUST_HTR "ON"
2001-DEC-5/07:30:42	2003-318/07:30:42	43313378	1	SEC_BC_THRUST_HTR "ON"
2001-DEC-5/07:31:19	2003-318/07:31:19	43313415	37	PRI_LV_LINE_HTR_HI "ON"
2001-DEC-5/07:31:19	2003-318/07:31:19	43313415	0	SEC_LV_LINE_HTR_HI "ON"
2001-DEC-5/07:31:29	2003-318/07:31:29	43313425	10	PRI_LV_LINE_HTR_LO "ON"
2001-DEC-5/07:31:29	2003-318/07:31:29	43313425	0	SEC_LV_LINE_HTR_LO "ON"
2001-DEC-5/07:58:59	2003-318/07:58:59	43315075	1650	PRI_DV_CAT_HTR "ON"
2001-DEC-5/07:58:59	2003-318/07:58:59	43315075	0	SEC_DV_CAT_HTR "ON"
2001-DEC-5/08:57:59	2003-318/08:57:59	43318615	3540	MACRO_START "CDH","OCM1_BURN",0,-1
2001-DEC-5/08:57:59	2003-318/08:57:59	43318615	0	CD_DELTAV_SETUP 12288,840,802

Mission Sim 1 Timeline

2001-DEC-5/08:58:09	2003-318/08:58:09	43318625	10	PRI_TANK_HTR "ON"
2001-DEC-5/08:58:09	2003-318/08:58:09	43318625	0	SEC_TANK_HTR "ON"
2001-DEC-5/08:58:14	2003-318/08:58:14	43318630	5	PRI_THRUST_LV_SEL "ENABLE"
2001-DEC-5/08:58:14	2003-318/08:58:14	43318630	0	SEC_THRUST_LV_SEL "ENABLE"
2001-DEC-5/08:58:44	2003-318/08:58:44	43318660	30	PRI_THRUST_LV_SEL "DISABLE"
2001-DEC-5/08:58:44	2003-318/08:58:44	43318660	0	SEC_THRUST_LV_SEL "DISABLE"
2001-DEC-5/08:59:39	2003-318/08:59:39	43318715	55	PRI_THRUST_LV_SEL "ENABLE"
2001-DEC-5/08:59:39	2003-318/08:59:39	43318715	0	SEC_THRUST_LV_SEL "ENABLE"
2001-DEC-5/08:59:41	2003-318/08:59:41	43318717	2	PRI_THRUST_ARM "ARM"
2001-DEC-5/08:59:44	2003-318/08:59:44	43318720	3	PRI_DV_CAT_HTR "OFF"
2001-DEC-5/08:59:44	2003-318/08:59:44	43318720	0	SEC_DV_CAT_HTR "OFF"
2001-DEC-5/08:59:44	2003-318/08:59:44	43318720	0	PRI_SPINUP_CAT_HTR "OFF"
2001-DEC-5/08:59:44	2003-318/08:59:44	43318720	0	SEC_SPINUP_CAT_HTR "OFF"
2001-DEC-5/08:59:44	2003-318/08:59:44	43318720	0	PRI_SPINDN_CAT_HTR "OFF"
2001-DEC-5/08:59:44	2003-318/08:59:44	43318720	0	SEC_SPINDN_CAT_HTR "OFF"
2001-DEC-5/08:59:44	2003-318/08:59:44	43318720	0	PRI_RADIAL_CAT_HTR "OFF"
2001-DEC-5/08:59:44	2003-318/08:59:44	43318720	0	SEC_RADIAL_CAT_HTR "OFF"
2001-DEC-5/08:59:57	2003-318/08:59:57	43318733	13	CD DELTAV FIRE
2001-DEC-5/09:06:46	2003-318/09:06:46	43319142	409	CD_TAC_MODE "OFF"
2001-DEC-5/09:06:47	2003-318/09:06:47	43319143	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/09:06:47	2003-318/09:06:47	43319143	0	PRI_THRUST_ARM "SAFE"
2001-DEC-5/09:06:47	2003-318/09:06:47	43319143	0	SEC_THRUST_ARM "SAFE"
2001-DEC-5/09:07:02	2003-318/09:07:02	43319158	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/09:07:02	2003-318/09:07:02	43319158	0	MACRO_END
2001-DEC-5/09:08:11	2003-318/09:08:11	43319227	69	MACRO_START "CDH","burn_shutdown",0,-1
2001-DEC-5/09:08:11	2003-318/09:08:11	43319227	0	CD_TAC_MODE "OFF"
2001-DEC-5/09:08:11	2003-318/09:08:11	43319227	0	PRI_THRUST_LV_SEL "ENABLE"
2001-DEC-5/09:08:11	2003-318/09:08:11	43319227	0	SEC_THRUST_LV_SEL "ENABLE"
2001-DEC-5/09:08:12	2003-318/09:08:12	43319228	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/09:08:13	2003-318/09:08:13	43319229	1	PRI_THRUST_ARM "SAFE"
2001-DEC-5/09:08:13	2003-318/09:08:13	43319229	0	SEC_THRUST_ARM "SAFE"
2001-DEC-5/09:08:21	2003-318/09:08:21	43319237	8	PRI_THRUST_LV_SEL "DISABLE"
2001-DEC-5/09:08:21	2003-318/09:08:21	43319237	0	SEC_THRUST_LV_SEL "DISABLE"
2001-DEC-5/09:08:27	2003-318/09:08:27	43319243	6	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/09:08:31	2003-318/09:08:31	43319247	4	PRI_LV_LINE_HTR_HI "ON"
2001-DEC-5/09:08:31	2003-318/09:08:31	43319247	0	PRI_LV_LINE_HTR_LO "ON"
2001-DEC-5/09:08:31	2003-318/09:08:31	43319247	0	SEC_LV_LINE_HTR_HI "ON"
2001-DEC-5/09:08:31	2003-318/09:08:31	43319247	0	SEC_LV_LINE_HTR_LO "ON"
2001-DEC-5/09:08:41	2003-318/09:08:41	43319257	10	PRI_DV_CAT_HTR "OFF"
2001-DEC-5/09:08:41	2003-318/09:08:41	43319257	0	SEC_DV_CAT_HTR "OFF"
2001-DEC-5/09:08:41	2003-318/09:08:41	43319257	0	PRI_SPINUP_CAT_HTR "OFF"
2001-DEC-5/09:08:41	2003-318/09:08:41	43319257	0	SEC_SPINUP_CAT_HTR "OFF"
2001-DEC-5/09:08:41	2003-318/09:08:41	43319257	0	PRI_SPINDN_CAT_HTR "OFF"
2001-DEC-5/09:08:41	2003-318/09:08:41	43319257	0	SEC_SPINDN_CAT_HTR "OFF"

Mission Sim 1 Timeline

2001-DEC-5/09:08:41	2003-318/09:08:41	43319257	0	PRI_RADIAL_CAT_HTR "OFF"
2001-DEC-5/09:08:41	2003-318/09:08:41	43319257	0	SEC_RADIAL_CAT_HTR "OFF"
2001-DEC-5/09:08:46	2003-318/09:08:46	43319262	5	PRI_TANK_HTR "ON"
2001-DEC-5/09:08:46	2003-318/09:08:46	43319262	0	SEC_TANK_HTR "ON"
2001-DEC-5/09:08:51	2003-318/09:08:51	43319267	5	PRI_AD_THRUST_HTR "ON"
2001-DEC-5/09:08:56	2003-318/09:08:56	43319272	5	SEC_AD_THRUST_HTR "ON"
2001-DEC-5/09:09:01	2003-318/09:09:01	43319277	5	PRI_BC_THRUST_HTR "ON"
2001-DEC-5/09:09:06	2003-318/09:09:06	43319282	5	SEC_BC_THRUST_HTR "ON"
2001-DEC-5/09:09:06	2003-318/09:09:06	43319282	0	MACRO_END
2001-DEC-5/09:09:21	2003-318/09:09:21	43319297	15	GC_ADD_TLM 0,0
2001-DEC-5/09:09:41	2003-318/09:09:41	43319317	20	SSR_LO_RCRD_ST "DISABLE"
2001-DEC-5/09:09:41	2003-318/09:09:41	43319317	0	SSR_WRT_PNTR_SV "LOW",5
2001-DEC-5/09:09:41	2003-318/09:09:41	43319317	0	SSR_PTR_SET "LOW",1311232
2001-DEC-5/09:09:41	2003-318/09:09:41	43319317	0	SSR_LO_RCRD_CTL "CONT",0
2001-DEC-5/09:09:42	2003-318/09:09:42	43319318	1	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-5/09:29:59	2003-318/09:29:59	43320535	1217	MACRO_START "CDH","OBB_ASPIN_3AXIS",0,988
2001-DEC-5/09:29:59	2003-318/09:29:59	43320535	0	PS_PRI_TLM_PROP "ON"
2001-DEC-5/09:30:00	2003-318/09:30:00	43320536	1	PS_SEC_TLM_PROP "ON"
2001-DEC-5/09:30:01	2003-318/09:30:01	43320537	1	PRI_SPINUP_CAT_HTR "ON"
2001-DEC-5/09:30:02	2003-318/09:30:02	43320538	1	PRI_SPINDN_CAT_HTR "ON"
2001-DEC-5/09:30:03	2003-318/09:30:03	43320539	1	PRI_RADIAL_CAT_HTR "ON"
2001-DEC-5/09:30:04	2003-318/09:30:04	43320540	1	PRI_DV_CAT_HTR "OFF"
2001-DEC-5/09:30:05	2003-318/09:30:05	43320541	1	SEC_SPINUP_CAT_HTR "ON"
2001-DEC-5/09:30:06	2003-318/09:30:06	43320542	1	SEC_SPINDN_CAT_HTR "ON"
2001-DEC-5/09:30:07	2003-318/09:30:07	43320543	1	SEC_RADIAL_CAT_HTR "ON"
2001-DEC-5/09:30:08	2003-318/09:30:08	43320544	1	SEC_DV_CAT_HTR "OFF"
2001-DEC-5/09:30:09	2003-318/09:30:09	43320545	1	PRI_AD_THRUST_HTR "ON"
2001-DEC-5/09:30:10	2003-318/09:30:10	43320546	1	PRI_BC_THRUST_HTR "ON"
2001-DEC-5/09:30:11	2003-318/09:30:11	43320547	1	SEC_AD_THRUST_HTR "ON"
2001-DEC-5/09:30:12	2003-318/09:30:12	43320548	1	SEC_BC_THRUST_HTR "ON"
2001-DEC-5/09:30:13	2003-318/09:30:13	43320549	1	PRI_LV_LINE_HTR_HI "ON"
2001-DEC-5/09:30:14	2003-318/09:30:14	43320550	1	SEC_LV_LINE_HTR_HI "ON"
2001-DEC-5/09:30:15	2003-318/09:30:15	43320551	1	PRI_LV_LINE_HTR_LO "ON"
2001-DEC-5/09:30:16	2003-318/09:30:16	43320552	1	SEC_LV_LINE_HTR_LO "ON"
2001-DEC-5/09:30:17	2003-318/09:30:17	43320553	1	PRI_SC_SV_HTR "ON"
2001-DEC-5/09:30:18	2003-318/09:30:18	43320554	1	SEC_SC_SV_HTR "ON"
2001-DEC-5/09:30:19	2003-318/09:30:19	43320555	1	PRI_TANK_HTR "ON"
2001-DEC-5/09:30:20	2003-318/09:30:20	43320556	1	SEC_TANK_HTR "ON"
2001-DEC-5/09:30:21	2003-318/09:30:21	43320557	1	ESS_PWR "ON"
2001-DEC-5/09:30:22	2003-318/09:30:22	43320558	1	ST_PWR "ON"
2001-DEC-5/09:30:23	2003-318/09:30:23	43320559	1	GYRO_PWR "ON"
2001-DEC-5/09:31:08	2003-318/09:31:08	43320604	45	I1_GC1_PWR "ON"
2001-DEC-5/09:31:09	2003-318/09:31:09	43320605	1	I2_GC2_PWR "ON"
2001-DEC-5/09:31:39	2003-318/09:31:39	43320635	30	GCBLOAD_EXE_FLAT_OFP

Mission Sim 1 Timeline

2001-DEC-5/09:32:09	2003-318/09:32:09	43320665	30	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/09:32:14	2003-318/09:32:14	43320670	5	GC_ST_SELECT "BOTH"
2001-DEC-5/09:32:14	2003-318/09:32:14	43320670	0	GC_IRU_FLTR "ENABLE"
2001-DEC-5/09:32:15	2003-318/09:32:15	43320671	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/09:32:15	2003-318/09:32:15	43320671	0	GCBLOAD_EXE_FLAT_OFF
2001-DEC-5/09:32:45	2003-318/09:32:45	43320701	30	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/09:32:50	2003-318/09:32:50	43320706	5	GC_ST_SELECT "BOTH"
2001-DEC-5/09:32:50	2003-318/09:32:50	43320706	0	GC_IRU_FLTR "ENABLE"
2001-DEC-5/09:32:50	2003-318/09:32:50	43320706	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/09:32:51	2003-318/09:32:51	43320707	1	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-5/09:59:51	2003-318/09:59:51	43322327	1620	PRI_THRUST_LV_SEL "ENABLE"
2001-DEC-5/09:59:52	2003-318/09:59:52	43322328	1	SEC_THRUST_LV_SEL "ENABLE"
2001-DEC-5/10:00:14	2003-318/10:00:14	43322350	22	PRI_THRUST_ARM "ARM"
2001-DEC-5/10:00:15	2003-318/10:00:15	43322351	1	SEC_THRUST_ARM "ARM"
2001-DEC-5/10:00:16	2003-318/10:00:16	43322352	1	CD_TAC_MODE "OFF"
2001-DEC-5/10:00:17	2003-318/10:00:17	43322353	1	CD_GC_MODE "3AXIS"
2001-DEC-5/10:00:18	2003-318/10:00:18	43322354	1	CD_GC_SCEN_SEL 4
2001-DEC-5/10:00:19	2003-318/10:00:19	43322355	1	CD_TAC_MODE "3AXIS"
2001-DEC-5/10:00:20	2003-318/10:00:20	43322356	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/10:00:35	2003-318/10:00:35	43322371	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/10:00:50	2003-318/10:00:50	43322386	15	CD_THREE_AX_SETUP 4095
2001-DEC-5/10:00:51	2003-318/10:00:51	43322387	1	GC_MODE_BIT0_SPIN_3A "3_AXIS"
2001-DEC-5/10:00:51	2003-318/10:00:51	43322387	0	GC_MODE_BIT1_NM_SPEC "NORMAL"
2001-DEC-5/10:00:52	2003-318/10:00:52	43322388	1	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",420,420
2001-DEC-5/10:00:53	2003-318/10:00:53	43322389	1	AUT_RUL_LOAD 420,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",20,20,"VALUE","EQUALS","UNSIGN"
2001-DEC-5/10:00:53	2003-318/10:00:53	43322389	0	EXECUTE_MACRO "OBB_3AXIS_S1Q"
2001-DEC-5/10:00:58	2003-318/10:00:58	43322394	5	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",420,420
2001-DEC-5/10:00:58	2003-318/10:00:58	43322394	0	MACRO_END
2001-DEC-5/10:18:59	2003-318/10:18:59	43323475	1081	GC_ADD_TLM 1,256
2001-DEC-5/10:18:59	2003-318/10:18:59	43323475	0	CD_GC_SCEN_SEL 3
2001-DEC-5/10:19:00	2003-318/10:19:00	43323476	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/10:19:15	2003-318/10:19:15	43323491	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/10:23:59	2003-318/10:23:59	43323775	284	GC_ADD_TLM 0,0
2001-DEC-5/10:24:00	2003-318/10:24:00	43323776	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-5/10:24:00	2003-318/10:24:00	43323776	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-5/10:24:01	2003-318/10:24:01	43323777	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/10:24:02	2003-318/10:24:02	43323778	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/10:24:02	2003-318/10:24:02	43323778	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/10:24:02	2003-318/10:24:02	43323778	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/10:24:02	2003-318/10:24:02	43323778	0	MACRO_END
2001-DEC-5/10:25:29	2003-318/10:25:29	43323865	87	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA",0,597
2001-DEC-5/10:25:29	2003-318/10:25:29	43323865	0	RF_BEAM_2 "OFF"
2001-DEC-5/10:25:29	2003-318/10:25:29	43323865	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-5/10:25:29	2003-318/10:25:29	43323865	0	RF_TWT_2_PWR "OFF"

Mission Sim 1 Timeline

2001-DEC-5/10:25:30	2003-318/10:25:30	43323866	1	RF_BEAM_1 "OFF"
2001-DEC-5/10:25:31	2003-318/10:25:31	43323867	1	RF_SW1_SEL_ANT "HGA"
2001-DEC-5/10:25:31	2003-318/10:25:31	43323867	0	RF_SW_TO_SW_SEL "SW2_TO_SW4"
2001-DEC-5/10:25:31	2003-318/10:25:31	43323867	0	RF_SW4_SEL_ANT "FLGA"
2001-DEC-5/10:25:31	2003-318/10:25:31	43323867	0	I1_RF_EXCITER "ON"
2001-DEC-5/10:25:32	2003-318/10:25:32	43323868	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-5/10:25:32	2003-318/10:25:32	43323868	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-5/10:25:32	2003-318/10:25:32	43323868	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-5/10:25:32	2003-318/10:25:32	43323868	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-5/10:25:33	2003-318/10:25:33	43323869	1	EXECUTE_MACRO "OBB_SIDE_1_HGA_FLGA_B"
2001-DEC-5/10:25:33	2003-318/10:25:33	43323869	0	MACRO_END
2001-DEC-5/10:25:33	2003-318/10:25:33	43323869	0	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA_B",0,598
2001-DEC-5/10:25:33	2003-318/10:25:33	43323869	0	CD_DL_RATE_SEL "51.1KHZ"
2001-DEC-5/10:25:33	2003-318/10:25:33	43323869	0	CD_DL_SUBC_MOD_ST_SEL "OFF"
2001-DEC-5/10:25:33	2003-318/10:25:33	43323869	0	CD_DL_MOD_INDX_SEL "HIGH"
2001-DEC-5/10:25:33	2003-318/10:25:33	43323869	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-5/10:25:34	2003-318/10:25:34	43323870	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-5/10:25:35	2003-318/10:25:35	43323871	1	CD_DL_SRC_SEL "RT"
2001-DEC-5/10:25:36	2003-318/10:25:36	43323872	1	RF_TWT_1_PWR "ON"
2001-DEC-5/10:25:37	2003-318/10:25:37	43323873	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-5/10:29:38	2003-318/10:29:38	43324114	241	RF_BEAM_1 "ON"
2001-DEC-5/10:29:38	2003-318/10:29:38	43324114	0	MACRO_END
2001-DEC-5/10:29:39	2003-318/10:29:39	43324115	1	MACRO_START "CDH","OBB_HI_TLM_RATES_1",0,603
2001-DEC-5/10:29:39	2003-318/10:29:39	43324115	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-5/10:29:39	2003-318/10:29:39	43324115	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-5/10:29:39	2003-318/10:29:39	43324115	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-5/10:29:39	2003-318/10:29:39	43324115	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-5/10:29:39	2003-318/10:29:39	43324115	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-5/10:29:40	2003-318/10:29:40	43324116	1	USE_REDUNDANT_SS "CDH"
2001-DEC-5/10:29:40	2003-318/10:29:40	43324116	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-5/10:29:40	2003-318/10:29:40	43324116	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-5/10:29:40	2003-318/10:29:40	43324116	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-5/10:29:40	2003-318/10:29:40	43324116	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-5/10:29:40	2003-318/10:29:40	43324116	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-5/10:29:40	2003-318/10:29:40	43324116	0	USE_PRIMARY_SS "CDH"
2001-DEC-5/10:29:40	2003-318/10:29:40	43324116	0	MACRO_END
2001-DEC-5/10:58:59	2003-318/10:58:59	43325875	1759	SSR_LO_RCRD_ST "DISABLE"
2001-DEC-5/10:58:59	2003-318/10:58:59	43325875	0	SSR_WRT_PNTR_SV "LOW",6
2001-DEC-5/10:58:59	2003-318/10:58:59	43325875	0	SSR_PTR_SET "HIGH",11264
2001-DEC-5/10:58:59	2003-318/10:58:59	43325875	0	CD_INSTR_TOT_PKT_CNT 2609564,100
2001-DEC-5/10:58:59	2003-318/10:58:59	43325875	0	SSR_USG_CNT_RES 7
2001-DEC-5/10:59:00	2003-318/10:59:00	43325876	1	SSR_HI_RCRD_ST "ENABLE"
2001-DEC-5/10:59:00	2003-318/10:59:00	43325876	0	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-5/10:59:01	2003-318/10:59:01	43325877	1	USE_REDUNDANT_SS "SSR"

Mission Sim 1 Timeline

2001-DEC-5/10:59:01	2003-318/10:59:01	43325877	0	SSR_PTR_SET "HIGH",11264
2001-DEC-5/10:59:01	2003-318/10:59:01	43325877	0	CD_INSTR_TOT_PKT_CNT 2609564,100
2001-DEC-5/10:59:01	2003-318/10:59:01	43325877	0	SSR_USG_CNT_RES 7
2001-DEC-5/10:59:02	2003-318/10:59:02	43325878	1	SSR_HI_RCRD_ST "ENABLE"
2001-DEC-5/10:59:02	2003-318/10:59:02	43325878	0	SSR_LO_RCRD_ST "ENABLE"
2001-DEC-5/10:59:02	2003-318/10:59:02	43325878	0	USE_PRIMARY_SS "SSR"
2001-DEC-5/10:59:27	2003-318/10:59:27	43325903	25	CD_DL_INTRLV_SEL "THIRTYTWO"
2001-DEC-5/10:59:27	2003-318/10:59:27	43325903	0	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-5/10:59:27	2003-318/10:59:27	43325903	0	AUT_RUL_LOAD 405,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",30,30,"VALUE","EQUALS","UNSIGN"
2001-DEC-5/10:59:27	2003-318/10:59:27	43325903	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_5"
2001-DEC-5/10:59:27	2003-318/10:59:27	43325903	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",405,405
2001-DEC-5/10:59:28	2003-318/10:59:28	43325904	1	AUT_RUL_LOAD 402,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",40,40,"VALUE","EQUALS","UNSIGN"
2001-DEC-5/10:59:28	2003-318/10:59:28	43325904	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_2"
2001-DEC-5/10:59:28	2003-318/10:59:28	43325904	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",402,402
2001-DEC-5/10:59:29	2003-318/10:59:29	43325905	1	AUT_RUL_LOAD 403,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",50,50,"VALUE","EQUALS","UNSIGN"
2001-DEC-5/10:59:29	2003-318/10:59:29	43325905	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_3"
2001-DEC-5/10:59:29	2003-318/10:59:29	43325905	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",403,403
2001-DEC-5/10:59:30	2003-318/10:59:30	43325906	1	AUT_RUL_LOAD 404,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",60,60,"VALUE","EQUALS","UNSIGN"
2001-DEC-5/10:59:30	2003-318/10:59:30	43325906	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_4"
2001-DEC-5/10:59:30	2003-318/10:59:30	43325906	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",404,404
2001-DEC-5/10:59:31	2003-318/10:59:31	43325907	1	AUT_RUL_LOAD 406,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",70,70,"VALUE","EQUALS","UNSIGN"
2001-DEC-5/10:59:31	2003-318/10:59:31	43325907	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_6"
2001-DEC-5/10:59:31	2003-318/10:59:31	43325907	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",406,406
2001-DEC-5/13:29:59	2003-318/13:29:59	43334935	9028	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-5/13:30:04	2003-318/13:30:04	43334940	5	CD_DL_SRC_SEL "RT"
2001-DEC-5/13:30:04	2003-318/13:30:04	43334940	0	SSR_PBACK "NUM_BLOCK",0,1
2001-DEC-5/13:45:29	2003-318/13:45:29	43335865	925	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN",0,593
2001-DEC-5/13:45:29	2003-318/13:45:29	43335865	0	RF_BEAM_2 "OFF"
2001-DEC-5/13:45:29	2003-318/13:45:29	43335865	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-5/13:45:29	2003-318/13:45:29	43335865	0	RF_TWT_2_PWR "OFF"
2001-DEC-5/13:45:30	2003-318/13:45:30	43335866	1	RF_BEAM_1 "OFF"
2001-DEC-5/13:45:31	2003-318/13:45:31	43335867	1	RF_SW_TO_SW_SEL "SW1_TO_SW3"
2001-DEC-5/13:45:31	2003-318/13:45:31	43335867	0	RF_SW3_SEL_ANT "FLGA"
2001-DEC-5/13:45:31	2003-318/13:45:31	43335867	0	RF_SW2_SEL_ANT "PANCAKE"
2001-DEC-5/13:45:31	2003-318/13:45:31	43335867	0	I1_RF_EXCITER "ON"
2001-DEC-5/13:45:32	2003-318/13:45:32	43335868	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-5/13:45:32	2003-318/13:45:32	43335868	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-5/13:45:32	2003-318/13:45:32	43335868	0	CD_DL_PARMS_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-5/13:45:32	2003-318/13:45:32	43335868	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-5/13:45:33	2003-318/13:45:33	43335869	1	EXECUTE_MACRO "OBB_SIDE_1_FLGA_PAN_B"
2001-DEC-5/13:45:33	2003-318/13:45:33	43335869	0	MACRO_END
2001-DEC-5/13:45:33	2003-318/13:45:33	43335869	0	MACRO_START "CDH","OBB_SIDE_1_FLGA_PAN_B",0,594
2001-DEC-5/13:45:33	2003-318/13:45:33	43335869	0	CD_DL_RATE_SEL "12.5HZ"
2001-DEC-5/13:45:33	2003-318/13:45:33	43335869	0	CD_DL_SUBC_MOD_ST_SEL "ON"

Mission Sim 1 Timeline

2001-DEC-5/13:45:33	2003-318/13:45:33	43335869	0	CD_DL_MOD_INDX_SEL "LOW"
2001-DEC-5/13:45:33	2003-318/13:45:33	43335869	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-5/13:45:34	2003-318/13:45:34	43335870	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-5/13:45:35	2003-318/13:45:35	43335871	1	CD_DL_SRC_SEL "RT"
2001-DEC-5/13:45:36	2003-318/13:45:36	43335872	1	RF_TWT_1_PWR "ON"
2001-DEC-5/13:45:37	2003-318/13:45:37	43335873	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-5/13:49:38	2003-318/13:49:38	43336114	241	RF_BEAM_1 "ON"
2001-DEC-5/13:49:38	2003-318/13:49:38	43336114	0	MACRO_END
2001-DEC-5/13:49:39	2003-318/13:49:39	43336115	1	MACRO_START "CDH","OBB_LO_TLM_RATES_1",0,604
2001-DEC-5/13:49:39	2003-318/13:49:39	43336115	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-5/13:49:39	2003-318/13:49:39	43336115	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-5/13:49:39	2003-318/13:49:39	43336115	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-5/13:49:39	2003-318/13:49:39	43336115	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-5/13:49:39	2003-318/13:49:39	43336115	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-5/13:49:40	2003-318/13:49:40	43336116	1	USE_REDUNDANT_SS "CDH"
2001-DEC-5/13:49:40	2003-318/13:49:40	43336116	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",10
2001-DEC-5/13:49:40	2003-318/13:49:40	43336116	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",30
2001-DEC-5/13:49:40	2003-318/13:49:40	43336116	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",30
2001-DEC-5/13:49:40	2003-318/13:49:40	43336116	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",30
2001-DEC-5/13:49:40	2003-318/13:49:40	43336116	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",30
2001-DEC-5/13:49:40	2003-318/13:49:40	43336116	0	USE_PRIMARY_SS "CDH"
2001-DEC-5/13:49:40	2003-318/13:49:40	43336116	0	MACRO_END
2001-DEC-5/17:59:59	2003-318/17:59:59	43351135	15019	GC_ADD_TLM 1,256
2001-DEC-5/17:59:59	2003-318/17:59:59	43351135	0	GC_RTW_UP_PARM_LPB12_DEF 0.00000000000000,4.00000000000000,0.00000000000000,0.00000000
2001-DEC-5/18:00:00	2003-318/18:00:00	43351136	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:00:00	2003-318/18:00:00	43351136	0	GC_RTW_UP_PARM_LPB12_DEF 0.00000000000000,4.00000000000000,0.00000000000000,0.00000000
2001-DEC-5/18:00:01	2003-318/18:00:01	43351137	1	USE_PRIMARY_SS "GNC"
2001-DEC-5/18:00:04	2003-318/18:00:04	43351140	3	CD_GC_SCEN_SEL 5
2001-DEC-5/18:00:05	2003-318/18:00:05	43351141	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/18:00:20	2003-318/18:00:20	43351156	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/18:00:24	2003-318/18:00:24	43351160	4	GC_ADD_TLM 0,0
2001-DEC-5/18:00:25	2003-318/18:00:25	43351161	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-5/18:00:25	2003-318/18:00:25	43351161	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,2
2001-DEC-5/18:00:26	2003-318/18:00:26	43351162	1	GC_RTW_UP_PARM_LPB26_DEF 0.00000000000000,0.00000000000000,0.00000000000000
2001-DEC-5/18:00:27	2003-318/18:00:27	43351163	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:00:27	2003-318/18:00:27	43351163	0	GC_RTW_UP_PARM_LPB26_DEF 0.00000000000000,0.00000000000000,0.00000000000000
2001-DEC-5/18:00:27	2003-318/18:00:27	43351163	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/18:00:27	2003-318/18:00:27	43351163	0	MACRO_END
2001-DEC-5/18:00:33	2003-318/18:00:33	43351169	6	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/18:00:37	2003-318/18:00:37	43351173	4	CFI_IMG_COMP_ALG "HIGH_RANGE","EXECUTE"
2001-DEC-5/18:00:37	2003-318/18:00:37	43351173	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:00:37	2003-318/18:00:37	43351173	0	CFI_IMG_FORMAT "512_512_REBIN","EXECUTE"
2001-DEC-5/18:00:37	2003-318/18:00:37	43351173	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/18:00:38	2003-318/18:00:38	43351174	1	CFI_IMG_EXP 1,5,"EXECUTE"

Mission Sim 1 Timeline

2001-DEC-5/18:00:38	2003-318/18:00:38	43351174	0	CFI_IMG_IMAGE 29,7,"EXECUTE"
2001-DEC-5/18:00:39	2003-318/18:00:39	43351175	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/18:00:46	2003-318/18:00:46	43351182	7	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/18:00:53	2003-318/18:00:53	43351189	7	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/18:01:00	2003-318/18:01:00	43351196	7	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/18:01:18	2003-318/18:01:18	43351214	18	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-5/18:01:22	2003-318/18:01:22	43351218	4	CFI_IMG_COMP_ALG "LOW_END","EXECUTE"
2001-DEC-5/18:01:22	2003-318/18:01:22	43351218	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:01:22	2003-318/18:01:22	43351218	0	CFI_IMG_FORMAT "256_256_REBIN","EXECUTE"
2001-DEC-5/18:01:22	2003-318/18:01:22	43351218	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/18:01:23	2003-318/18:01:23	43351219	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:01:23	2003-318/18:01:23	43351219	0	CFI_IMG_IMAGE 10,9,"EXECUTE"
2001-DEC-5/18:01:24	2003-318/18:01:24	43351220	1	CFI_FLT_MOVE 9,"EXECUTE"
2001-DEC-5/18:01:49	2003-318/18:01:49	43351245	25	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/18:01:53	2003-318/18:01:53	43351249	4	CFI_IMG_COMP_ALG "MID_RANGE","EXECUTE"
2001-DEC-5/18:01:53	2003-318/18:01:53	43351249	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:01:53	2003-318/18:01:53	43351249	0	CFI_IMG_FORMAT "256_256_WINDOW","EXECUTE"
2001-DEC-5/18:01:53	2003-318/18:01:53	43351249	0	CFI_IMG_REGION 384,384,"EXECUTE"
2001-DEC-5/18:01:54	2003-318/18:01:54	43351250	1	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:01:54	2003-318/18:01:54	43351250	0	CFI_IMG_IMAGE 22,3,"EXECUTE"
2001-DEC-5/18:01:55	2003-318/18:01:55	43351251	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/18:01:58	2003-318/18:01:58	43351254	3	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/18:02:01	2003-318/18:02:01	43351257	3	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/18:02:04	2003-318/18:02:04	43351260	3	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/18:02:07	2003-318/18:02:07	43351263	3	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-5/18:02:10	2003-318/18:02:10	43351266	3	CFI_FLT_MOVE 7,"EXECUTE"
2001-DEC-5/18:02:13	2003-318/18:02:13	43351269	3	CFI_FLT_MOVE 8,"EXECUTE"
2001-DEC-5/18:02:29	2003-318/18:02:29	43351285	16	GC_ADD_TLM 1,256
2001-DEC-5/18:02:29	2003-318/18:02:29	43351285	0	CD_GC_SCEN_SEL 4
2001-DEC-5/18:02:30	2003-318/18:02:30	43351286	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/18:02:45	2003-318/18:02:45	43351301	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/18:07:29	2003-318/18:07:29	43351585	284	GC_ADD_TLM 0,0
2001-DEC-5/18:07:30	2003-318/18:07:30	43351586	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-5/18:07:30	2003-318/18:07:30	43351586	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-5/18:07:31	2003-318/18:07:31	43351587	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/18:07:32	2003-318/18:07:32	43351588	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:07:32	2003-318/18:07:32	43351588	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/18:07:32	2003-318/18:07:32	43351588	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/18:07:32	2003-318/18:07:32	43351588	0	MACRO_END
2001-DEC-5/18:14:59	2003-318/18:14:59	43352035	447	GC_ADD_TLM 1,256
2001-DEC-5/18:14:59	2003-318/18:14:59	43352035	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/18:15:00	2003-318/18:15:00	43352036	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:15:00	2003-318/18:15:00	43352036	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/18:15:01	2003-318/18:15:01	43352037	1	USE_PRIMARY_SS "GNC"

Mission Sim 1 Timeline

2001-DEC-5/18:15:04	2003-318/18:15:04	43352040	3	CD_GC_SCEN_SEL 5
2001-DEC-5/18:15:05	2003-318/18:15:05	43352041	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/18:15:20	2003-318/18:15:20	43352056	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/18:15:24	2003-318/18:15:24	43352060	4	GC_ADD_TLM 0,0
2001-DEC-5/18:15:25	2003-318/18:15:25	43352061	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-5/18:15:25	2003-318/18:15:25	43352061	0	ASC_LOAD_PARAM_TC 071 "NO_ACK",71,1,2
2001-DEC-5/18:15:26	2003-318/18:15:26	43352062	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/18:15:27	2003-318/18:15:27	43352063	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:15:27	2003-318/18:15:27	43352063	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/18:15:27	2003-318/18:15:27	43352063	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/18:15:27	2003-318/18:15:27	43352063	0	MACRO_END
2001-DEC-5/18:15:33	2003-318/18:15:33	43352069	6	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/18:15:37	2003-318/18:15:37	43352073	4	CFI_IMG_COMP_ALG "ROOT_2","EXECUTE"
2001-DEC-5/18:15:37	2003-318/18:15:37	43352073	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:15:37	2003-318/18:15:37	43352073	0	CFI_IMG_FORMAT "512_512_REBIN","EXECUTE"
2001-DEC-5/18:15:37	2003-318/18:15:37	43352073	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/18:15:38	2003-318/18:15:38	43352074	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:15:38	2003-318/18:15:38	43352074	0	CFI_IMG_IMAGE 64,7,"EXECUTE"
2001-DEC-5/18:15:45	2003-318/18:15:45	43352081	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:15:46	2003-318/18:15:46	43352082	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/18:15:52	2003-318/18:15:52	43352088	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:15:59	2003-318/18:15:59	43352095	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:16:00	2003-318/18:16:00	43352096	1	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/18:16:06	2003-318/18:16:06	43352102	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:16:13	2003-318/18:16:13	43352109	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:16:14	2003-318/18:16:14	43352110	1	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/18:16:20	2003-318/18:16:20	43352116	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:16:27	2003-318/18:16:27	43352123	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:16:28	2003-318/18:16:28	43352124	1	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/18:16:34	2003-318/18:16:34	43352130	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:16:41	2003-318/18:16:41	43352137	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:16:58	2003-318/18:16:58	43352154	17	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-5/18:17:02	2003-318/18:17:02	43352158	4	CFI_IMG_COMP_ALG "LINEARR","EXECUTE"
2001-DEC-5/18:17:02	2003-318/18:17:02	43352158	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:17:02	2003-318/18:17:02	43352158	0	CFI_IMG_FORMAT "256_256_REBIN","EXECUTE"
2001-DEC-5/18:17:02	2003-318/18:17:02	43352158	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/18:17:03	2003-318/18:17:03	43352159	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:17:03	2003-318/18:17:03	43352159	0	CFI_IMG_IMAGE 28,9,"EXECUTE"
2001-DEC-5/18:17:12	2003-318/18:17:12	43352168	9	CFI_IMG_EXP 1,2,"EXECUTE"
2001-DEC-5/18:17:13	2003-318/18:17:13	43352169	1	CFI_FLT_MOVE 9,"EXECUTE"
2001-DEC-5/18:17:21	2003-318/18:17:21	43352177	8	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:17:30	2003-318/18:17:30	43352186	9	CFI_IMG_EXP 1,2,"EXECUTE"
2001-DEC-5/18:17:59	2003-318/18:17:59	43352215	29	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/18:18:03	2003-318/18:18:03	43352219	4	CFI_IMG_COMP_ALG "MID_RANGE","EXECUTE"

Mission Sim 1 Timeline

2001-DEC-5/18:18:03	2003-318/18:18:03	43352219	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:18:03	2003-318/18:18:03	43352219	0	CFI_IMG_FORMAT "512_512_WINDOW","EXECUTE"
2001-DEC-5/18:18:03	2003-318/18:18:03	43352219	0	CFI_IMG_REGION 384,384,"EXECUTE"
2001-DEC-5/18:18:04	2003-318/18:18:04	43352220	1	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:18:04	2003-318/18:18:04	43352220	0	CFI_IMG_IMAGE 46,3,"EXECUTE"
2001-DEC-5/18:18:07	2003-318/18:18:07	43352223	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:18:08	2003-318/18:18:08	43352224	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/18:18:10	2003-318/18:18:10	43352226	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:18:13	2003-318/18:18:13	43352229	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:18:14	2003-318/18:18:14	43352230	1	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/18:18:16	2003-318/18:18:16	43352232	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:18:19	2003-318/18:18:19	43352235	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:18:20	2003-318/18:18:20	43352236	1	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/18:18:22	2003-318/18:18:22	43352238	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:18:25	2003-318/18:18:25	43352241	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:18:26	2003-318/18:18:26	43352242	1	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/18:18:28	2003-318/18:18:28	43352244	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:18:31	2003-318/18:18:31	43352247	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:18:32	2003-318/18:18:32	43352248	1	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-5/18:18:34	2003-318/18:18:34	43352250	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:18:37	2003-318/18:18:37	43352253	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:18:38	2003-318/18:18:38	43352254	1	CFI_FLT_MOVE 7,"EXECUTE"
2001-DEC-5/18:18:40	2003-318/18:18:40	43352256	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:18:43	2003-318/18:18:43	43352259	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:18:44	2003-318/18:18:44	43352260	1	CFI_FLT_MOVE 8,"EXECUTE"
2001-DEC-5/18:18:46	2003-318/18:18:46	43352262	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:18:49	2003-318/18:18:49	43352265	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:19:39	2003-318/18:19:39	43352315	50	GC_ADD_TLM 1,256
2001-DEC-5/18:19:39	2003-318/18:19:39	43352315	0	CD_GC_SCEN_SEL 4
2001-DEC-5/18:19:40	2003-318/18:19:40	43352316	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/18:19:55	2003-318/18:19:55	43352331	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/18:24:39	2003-318/18:24:39	43352615	284	GC_ADD_TLM 0,0
2001-DEC-5/18:24:40	2003-318/18:24:40	43352616	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-5/18:24:40	2003-318/18:24:40	43352616	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-5/18:24:41	2003-318/18:24:41	43352617	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/18:24:42	2003-318/18:24:42	43352618	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:24:42	2003-318/18:24:42	43352618	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/18:24:42	2003-318/18:24:42	43352618	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/18:24:42	2003-318/18:24:42	43352618	0	MACRO_END
2001-DEC-5/18:29:59	2003-318/18:29:59	43352935	317	GC_ADD_TLM 1,256
2001-DEC-5/18:29:59	2003-318/18:29:59	43352935	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/18:30:00	2003-318/18:30:00	43352936	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:30:00	2003-318/18:30:00	43352936	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/18:30:01	2003-318/18:30:01	43352937	1	USE_PRIMARY_SS "GNC"

Mission Sim 1 Timeline

2001-DEC-5/18:30:04	2003-318/18:30:04	43352940	3	CD_GC_SCEN_SEL 5
2001-DEC-5/18:30:05	2003-318/18:30:05	43352941	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/18:30:20	2003-318/18:30:20	43352956	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/18:30:24	2003-318/18:30:24	43352960	4	GC_ADD_TLM 0,0
2001-DEC-5/18:30:25	2003-318/18:30:25	43352961	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-5/18:30:25	2003-318/18:30:25	43352961	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,2
2001-DEC-5/18:30:26	2003-318/18:30:26	43352962	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/18:30:27	2003-318/18:30:27	43352963	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:30:27	2003-318/18:30:27	43352963	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/18:30:27	2003-318/18:30:27	43352963	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/18:30:27	2003-318/18:30:27	43352963	0	MACRO_END
2001-DEC-5/18:30:33	2003-318/18:30:33	43352969	6	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/18:30:37	2003-318/18:30:37	43352973	4	CFI_IMG_COMP_ALG "HIGH_RANGE","EXECUTE"
2001-DEC-5/18:30:37	2003-318/18:30:37	43352973	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:30:37	2003-318/18:30:37	43352973	0	CFI_IMG_FORMAT "512_512_REBIN","EXECUTE"
2001-DEC-5/18:30:37	2003-318/18:30:37	43352973	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/18:30:38	2003-318/18:30:38	43352974	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:30:38	2003-318/18:30:38	43352974	0	CFI_IMG_IMAGE 64,7,"EXECUTE"
2001-DEC-5/18:30:45	2003-318/18:30:45	43352981	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:30:46	2003-318/18:30:46	43352982	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/18:30:52	2003-318/18:30:52	43352988	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:30:59	2003-318/18:30:59	43352995	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:31:00	2003-318/18:31:00	43352996	1	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/18:31:06	2003-318/18:31:06	43353002	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:31:13	2003-318/18:31:13	43353009	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:31:14	2003-318/18:31:14	43353010	1	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/18:31:20	2003-318/18:31:20	43353016	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:31:27	2003-318/18:31:27	43353023	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:31:28	2003-318/18:31:28	43353024	1	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/18:31:34	2003-318/18:31:34	43353030	6	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:31:41	2003-318/18:31:41	43353037	7	CFI_IMG_EXP 1,3,"EXECUTE"
2001-DEC-5/18:31:58	2003-318/18:31:58	43353054	17	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-5/18:32:02	2003-318/18:32:02	43353058	4	CFI_IMG_COMP_ALG "LOW_END","EXECUTE"
2001-DEC-5/18:32:02	2003-318/18:32:02	43353058	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:32:02	2003-318/18:32:02	43353058	0	CFI_IMG_FORMAT "256_256_REBIN","EXECUTE"
2001-DEC-5/18:32:02	2003-318/18:32:02	43353058	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/18:32:03	2003-318/18:32:03	43353059	1	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:32:03	2003-318/18:32:03	43353059	0	CFI_IMG_IMAGE 28,9,"EXECUTE"
2001-DEC-5/18:32:12	2003-318/18:32:12	43353068	9	CFI_IMG_EXP 1,2,"EXECUTE"
2001-DEC-5/18:32:13	2003-318/18:32:13	43353069	1	CFI_FLT_MOVE 9,"EXECUTE"
2001-DEC-5/18:32:21	2003-318/18:32:21	43353077	8	CFI_IMG_EXP 1,5,"EXECUTE"
2001-DEC-5/18:32:30	2003-318/18:32:30	43353086	9	CFI_IMG_EXP 1,2,"EXECUTE"
2001-DEC-5/18:32:59	2003-318/18:32:59	43353115	29	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/18:33:03	2003-318/18:33:03	43353119	4	CFI_IMG_COMP_ALG "MID_RANGE","EXECUTE"

Mission Sim 1 Timeline

2001-DEC-5/18:33:03	2003-318/18:33:03	43353119	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/18:33:03	2003-318/18:33:03	43353119	0	CFI_IMG_FORMAT "512_512_WINDOW","EXECUTE"
2001-DEC-5/18:33:03	2003-318/18:33:03	43353119	0	CFI_IMG_REGION 384,384,"EXECUTE"
2001-DEC-5/18:33:04	2003-318/18:33:04	43353120	1	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:33:04	2003-318/18:33:04	43353120	0	CFI_IMG_IMAGE 46,3,"EXECUTE"
2001-DEC-5/18:33:07	2003-318/18:33:07	43353123	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:33:08	2003-318/18:33:08	43353124	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/18:33:10	2003-318/18:33:10	43353126	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:33:13	2003-318/18:33:13	43353129	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:33:14	2003-318/18:33:14	43353130	1	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/18:33:16	2003-318/18:33:16	43353132	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:33:19	2003-318/18:33:19	43353135	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:33:20	2003-318/18:33:20	43353136	1	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/18:33:22	2003-318/18:33:22	43353138	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:33:25	2003-318/18:33:25	43353141	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:33:26	2003-318/18:33:26	43353142	1	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/18:33:28	2003-318/18:33:28	43353144	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:33:31	2003-318/18:33:31	43353147	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:33:32	2003-318/18:33:32	43353148	1	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-5/18:33:34	2003-318/18:33:34	43353150	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:33:37	2003-318/18:33:37	43353153	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:33:38	2003-318/18:33:38	43353154	1	CFI_FLT_MOVE 7,"EXECUTE"
2001-DEC-5/18:33:40	2003-318/18:33:40	43353156	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:33:43	2003-318/18:33:43	43353159	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:33:44	2003-318/18:33:44	43353160	1	CFI_FLT_MOVE 8,"EXECUTE"
2001-DEC-5/18:33:46	2003-318/18:33:46	43353162	2	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/18:33:49	2003-318/18:33:49	43353165	3	CFI_IMG_EXP 50,0,"EXECUTE"
2001-DEC-5/18:34:39	2003-318/18:34:39	43353215	50	GC_ADD_TLM 1,256
2001-DEC-5/18:34:39	2003-318/18:34:39	43353215	0	CD_GC_SCEN_SEL 4
2001-DEC-5/18:34:40	2003-318/18:34:40	43353216	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/18:34:55	2003-318/18:34:55	43353231	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/18:39:39	2003-318/18:39:39	43353515	284	GC_ADD_TLM 0,0
2001-DEC-5/18:39:40	2003-318/18:39:40	43353516	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-5/18:39:40	2003-318/18:39:40	43353516	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,1
2001-DEC-5/18:39:41	2003-318/18:39:41	43353517	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/18:39:42	2003-318/18:39:42	43353518	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/18:39:42	2003-318/18:39:42	43353518	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/18:39:42	2003-318/18:39:42	43353518	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/18:39:42	2003-318/18:39:42	43353518	0	MACRO_END
2001-DEC-5/19:54:59	2003-318/19:54:59	43358035	4517	GC_ADD_TLM 1,256
2001-DEC-5/19:54:59	2003-318/19:54:59	43358035	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/19:55:00	2003-318/19:55:00	43358036	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/19:55:00	2003-318/19:55:00	43358036	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/19:55:01	2003-318/19:55:01	43358037	1	USE_PRIMARY_SS "GNC"

Mission Sim 1 Timeline

2001-DEC-5/19:55:04	2003-318/19:55:04	43358040	3	CD_GC_SCEN_SEL 5
2001-DEC-5/19:55:05	2003-318/19:55:05	43358041	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/19:55:20	2003-318/19:55:20	43358056	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/19:55:24	2003-318/19:55:24	43358060	4	GC_ADD_TLM 0,0
2001-DEC-5/19:55:25	2003-318/19:55:25	43358061	1	MACRO_START "CDH","OBB_3AXIS_SZERO",0,578
2001-DEC-5/19:55:25	2003-318/19:55:25	43358061	0	ASC_LOAD_PARAM_TC_071 "NO_ACK",71,1,2
2001-DEC-5/19:55:26	2003-318/19:55:26	43358062	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/19:55:27	2003-318/19:55:27	43358063	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/19:55:27	2003-318/19:55:27	43358063	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,0.000000000000000
2001-DEC-5/19:55:27	2003-318/19:55:27	43358063	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/19:55:27	2003-318/19:55:27	43358063	0	MACRO_END
2001-DEC-5/19:55:33	2003-318/19:55:33	43358069	6	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/19:55:37	2003-318/19:55:37	43358073	4	CFI_IMG_COMP_ALG "DN_WEIGHTED","EXECUTE"
2001-DEC-5/19:55:37	2003-318/19:55:37	43358073	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/19:55:37	2003-318/19:55:37	43358073	0	CFI_IMG_FORMAT "1024_1024","EXECUTE"
2001-DEC-5/19:55:37	2003-318/19:55:37	43358073	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/19:55:38	2003-318/19:55:38	43358074	1	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/19:55:38	2003-318/19:55:38	43358074	0	CFI_IMG_IMAGE 22,3,"EXECUTE"
2001-DEC-5/19:55:39	2003-318/19:55:39	43358075	1	CFI_FLT_MOVE 2,"EXECUTE"
2001-DEC-5/19:55:42	2003-318/19:55:42	43358078	3	CFI_FLT_MOVE 3,"EXECUTE"
2001-DEC-5/19:55:45	2003-318/19:55:45	43358081	3	CFI_FLT_MOVE 4,"EXECUTE"
2001-DEC-5/19:55:48	2003-318/19:55:48	43358084	3	CFI_FLT_MOVE 5,"EXECUTE"
2001-DEC-5/19:55:51	2003-318/19:55:51	43358087	3	CFI_FLT_MOVE 6,"EXECUTE"
2001-DEC-5/19:55:54	2003-318/19:55:54	43358090	3	CFI_FLT_MOVE 7,"EXECUTE"
2001-DEC-5/19:55:57	2003-318/19:55:57	43358093	3	CFI_FLT_MOVE 8,"EXECUTE"
2001-DEC-5/19:56:22	2003-318/19:56:22	43358118	25	CFI_FLT_MOVE 1,"EXECUTE"
2001-DEC-5/19:56:26	2003-318/19:56:26	43358122	4	CFI_IMG_COMP_ALG "SNR_PROPORTIONAL","EXECUTE"
2001-DEC-5/19:56:26	2003-318/19:56:26	43358122	0	CFI_IMG_COMP_MODE "ENABLE","EXECUTE"
2001-DEC-5/19:56:26	2003-318/19:56:26	43358122	0	CFI_IMG_FORMAT "1024_1024","EXECUTE"
2001-DEC-5/19:56:26	2003-318/19:56:26	43358122	0	CFI_IMG_REGION 0,0,"EXECUTE"
2001-DEC-5/19:56:27	2003-318/19:56:27	43358123	1	CFI_IMG_EXP 37,0,"EXECUTE"
2001-DEC-5/19:56:27	2003-318/19:56:27	43358123	0	CFI_IMG_IMAGE 9,2,"EXECUTE"
2001-DEC-5/19:58:59	2003-318/19:58:59	43358275	152	GC_ADD_TLM 1,256
2001-DEC-5/19:58:59	2003-318/19:58:59	43358275	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/19:59:00	2003-318/19:59:00	43358276	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/19:59:00	2003-318/19:59:00	43358276	0	GC_RTW_UP_PARM_LPB12_DEF 0.000000000000000,4.000000000000000,0.000000000000000,0.00000000
2001-DEC-5/19:59:01	2003-318/19:59:01	43358277	1	USE_PRIMARY_SS "GNC"
2001-DEC-5/19:59:04	2003-318/19:59:04	43358280	3	CD_GC_SCEN_SEL 5
2001-DEC-5/19:59:05	2003-318/19:59:05	43358281	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/19:59:20	2003-318/19:59:20	43358296	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/19:59:34	2003-318/19:59:34	43358310	14	GC_ADD_TLM 0,0
2001-DEC-5/20:00:00	2003-318/20:00:00	43358336	26	Closest Approach
2001-DEC-5/20:58:59	2003-318/20:58:59	43361875	3565	GC_ADD_TLM 1,256
2001-DEC-5/20:58:59	2003-318/20:58:59	43361875	0	CD_GC_SCEN_SEL 3

Mission Sim 1 Timeline

2001-DEC-5/20:59:00	2003-318/20:59:00	43361876	1	CD_FLSHSEG_ER "PARAM"
2001-DEC-5/20:59:15	2003-318/20:59:15	43361891	15	CD_FLSHSEG_PRGM "PARAM"
2001-DEC-5/21:03:59	2003-318/21:03:59	43362175	284	GC_ADD_TLM 0,0
2001-DEC-5/21:04:00	2003-318/21:04:00	43362176	1	MACRO_START "CDH","OBB_3AXIS_S1Q",0,580
2001-DEC-5/21:04:00	2003-318/21:04:00	43362176	0	ASC_LOAD_PARAM_TC 071 "NO_ACK",71,1,1
2001-DEC-5/21:04:01	2003-318/21:04:01	43362177	1	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/21:04:02	2003-318/21:04:02	43362178	1	USE_REDUNDANT_SS "GNC"
2001-DEC-5/21:04:02	2003-318/21:04:02	43362178	0	GC_RTW_UP_PARM_LPB26_DEF 0.000000000000000,0.000000000000000,-0.026170000000000
2001-DEC-5/21:04:02	2003-318/21:04:02	43362178	0	USE_PRIMARY_SS "GNC"
2001-DEC-5/21:04:02	2003-318/21:04:02	43362178	0	MACRO_END
2001-DEC-5/21:05:29	2003-318/21:05:29	43362265	87	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA",0,597
2001-DEC-5/21:05:29	2003-318/21:05:29	43362265	0	RF_BEAM_2 "OFF"
2001-DEC-5/21:05:29	2003-318/21:05:29	43362265	0	RF_TWT_2_FILAMENT "OFF"
2001-DEC-5/21:05:29	2003-318/21:05:29	43362265	0	RF_TWT_2_PWR "OFF"
2001-DEC-5/21:05:30	2003-318/21:05:30	43362266	1	RF_BEAM_1 "OFF"
2001-DEC-5/21:05:31	2003-318/21:05:31	43362267	1	RF_SW1_SEL_ANT "HGA"
2001-DEC-5/21:05:31	2003-318/21:05:31	43362267	0	RF_SW_TO_SW_SEL "SW2_TO_SW4"
2001-DEC-5/21:05:31	2003-318/21:05:31	43362267	0	RF_SW4_SEL_ANT "FLGA"
2001-DEC-5/21:05:31	2003-318/21:05:31	43362267	0	I1_RF_EXCITER "ON"
2001-DEC-5/21:05:32	2003-318/21:05:32	43362268	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-5/21:05:32	2003-318/21:05:32	43362268	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-5/21:05:32	2003-318/21:05:32	43362268	0	CD_DL_PARMs_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-5/21:05:32	2003-318/21:05:32	43362268	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-5/21:05:33	2003-318/21:05:33	43362269	1	EXECUTE_MACRO "OBB_SIDE_1_HGA_FLGA_B"
2001-DEC-5/21:05:33	2003-318/21:05:33	43362269	0	MACRO_END
2001-DEC-5/21:05:33	2003-318/21:05:33	43362269	0	MACRO_START "CDH","OBB_SIDE_1_HGA_FLGA_B",0,598
2001-DEC-5/21:05:33	2003-318/21:05:33	43362269	0	CD_DL_RATE_SEL "51.1KHZ"
2001-DEC-5/21:05:33	2003-318/21:05:33	43362269	0	CD_DL_SUBC_MOD_ST_SEL "OFF"
2001-DEC-5/21:05:33	2003-318/21:05:33	43362269	0	CD_DL_MOD_INDX_SEL "HIGH"
2001-DEC-5/21:05:33	2003-318/21:05:33	43362269	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-5/21:05:34	2003-318/21:05:34	43362270	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-5/21:05:35	2003-318/21:05:35	43362271	1	CD_DL_SRC_SEL "RT"
2001-DEC-5/21:05:36	2003-318/21:05:36	43362272	1	RF_TWT_1_PWR "ON"
2001-DEC-5/21:05:37	2003-318/21:05:37	43362273	1	RF_TWT_1_FILAMENT "ON"
2001-DEC-5/21:09:38	2003-318/21:09:38	43362514	241	RF_BEAM_1 "ON"
2001-DEC-5/21:09:38	2003-318/21:09:38	43362514	0	MACRO_END
2001-DEC-5/21:09:39	2003-318/21:09:39	43362515	1	MACRO_START "CDH","OBB_HI_TLM_RATES_1",0,603
2001-DEC-5/21:09:39	2003-318/21:09:39	43362515	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-5/21:09:39	2003-318/21:09:39	43362515	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-5/21:09:39	2003-318/21:09:39	43362515	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-5/21:09:39	2003-318/21:09:39	43362515	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-5/21:09:39	2003-318/21:09:39	43362515	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-5/21:09:40	2003-318/21:09:40	43362516	1	USE_REDUNDANT_SS "CDH"
2001-DEC-5/21:09:40	2003-318/21:09:40	43362516	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1

Mission Sim 1 Timeline

2001-DEC-5/21:09:40	2003-318/21:09:40	43362516	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-5/21:09:40	2003-318/21:09:40	43362516	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-5/21:09:40	2003-318/21:09:40	43362516	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-5/21:09:40	2003-318/21:09:40	43362516	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-5/21:09:40	2003-318/21:09:40	43362516	0	USE_PRIMARY_SS "CDH"
2001-DEC-5/21:09:40	2003-318/21:09:40	43362516	0	MACRO_END
2001-DEC-5/21:24:29	2003-318/21:24:29	43363405	889	SSR_HI_RCRD_ST "DISABLE"
2001-DEC-5/21:24:29	2003-318/21:24:29	43363405	0	SSR_WRT_PNTR_SV "HIGH",1
2001-DEC-5/21:39:27	2003-318/21:39:27	43364303	898	CD_DL_INTRLV_SEL "THIRTYTWO"
2001-DEC-5/21:39:27	2003-318/21:39:27	43364303	0	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-5/21:39:27	2003-318/21:39:27	43364303	0	AUT_RUL_LOAD 401,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",30,30,"VALUE","EQUALS","UNSIGN"
2001-DEC-5/21:39:27	2003-318/21:39:27	43364303	0	EXECUTE_MACRO "OBB_SSR1_PB_SEG_1"
2001-DEC-5/21:39:27	2003-318/21:39:27	43364303	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",401,401
2001-DEC-5/21:59:59	2003-318/21:59:59	43365535	1232	NGI_PWR "OFF"
2001-DEC-6/02:39:59	2003-319/02:39:59	43382335	16800	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-6/02:40:04	2003-319/02:40:04	43382340	5	CD_DL_SRC_SEL "RT"
2001-DEC-6/02:40:04	2003-319/02:40:04	43382340	0	SSR_PBACK "NUM_BLOCK",0,1
2001-DEC-6/02:55:29	2003-319/02:55:29	43383265	925	MACRO_START "CDH","OBB_SIDE_2_HGA_FLGA",0,597
2001-DEC-6/02:55:29	2003-319/02:55:29	43383265	0	RF_BEAM_1 "OFF"
2001-DEC-6/02:55:29	2003-319/02:55:29	43383265	0	RF_TWT_1_FILAMENT "OFF"
2001-DEC-6/02:55:29	2003-319/02:55:29	43383265	0	RF_TWT_1_PWR "OFF"
2001-DEC-6/02:55:30	2003-319/02:55:30	43383266	1	RF_BEAM_2 "OFF"
2001-DEC-6/02:55:31	2003-319/02:55:31	43383267	1	RF_SW_TO_SW_SEL "SW1_TO_SW3"
2001-DEC-6/02:55:31	2003-319/02:55:31	43383267	0	RF_SW3_SEL_ANT "FLGA"
2001-DEC-6/02:55:31	2003-319/02:55:31	43383267	0	RF_SW2_SEL_ANT "HGA"
2001-DEC-6/02:55:31	2003-319/02:55:31	43383267	0	I2_RF_EXCITER "ON"
2001-DEC-6/02:55:32	2003-319/02:55:32	43383268	1	CD_DL_COH_SIM_ST_SEL "AUTO"
2001-DEC-6/02:55:32	2003-319/02:55:32	43383268	0	CD_DL_MOD_ST_SEL "ON"
2001-DEC-6/02:55:32	2003-319/02:55:32	43383268	0	CD_DL_PARMs_ST_SEL "SW","ENCODE","RND_OFF","RS_ON"
2001-DEC-6/02:55:32	2003-319/02:55:32	43383268	0	CD_DL_EMER_TONE_ST_SEL "OFF"
2001-DEC-6/02:55:33	2003-319/02:55:33	43383269	1	EXECUTE_MACRO "OBB_SIDE_2_HGA_FLGA_B"
2001-DEC-6/02:55:33	2003-319/02:55:33	43383269	0	MACRO_END
2001-DEC-6/02:55:33	2003-319/02:55:33	43383269	0	MACRO_START "CDH","OBB_SIDE_2_HGA_FLGA_B",0,598
2001-DEC-6/02:55:33	2003-319/02:55:33	43383269	0	CD_DL_RATE_SEL "51.1KHZ"
2001-DEC-6/02:55:33	2003-319/02:55:33	43383269	0	CD_DL_SUBC_MOD_ST_SEL "OFF"
2001-DEC-6/02:55:33	2003-319/02:55:33	43383269	0	CD_DL_MOD_INDX_SEL "HIGH"
2001-DEC-6/02:55:33	2003-319/02:55:33	43383269	0	CD_DL_RNG_ST_SEL "ON"
2001-DEC-6/02:55:34	2003-319/02:55:34	43383270	1	CD_DL_CONV_RT_SEL "RATE1_6"
2001-DEC-6/02:55:35	2003-319/02:55:35	43383271	1	CD_DL_SRC_SEL "RT"
2001-DEC-6/02:55:36	2003-319/02:55:36	43383272	1	RF_TWT_2_PWR "ON"
2001-DEC-6/02:55:37	2003-319/02:55:37	43383273	1	RF_TWT_2_FILAMENT "ON"
2001-DEC-6/02:59:38	2003-319/02:59:38	43383514	241	RF_BEAM_2 "ON"
2001-DEC-6/02:59:38	2003-319/02:59:38	43383514	0	MACRO_END
2001-DEC-6/02:59:39	2003-319/02:59:39	43383515	1	MACRO_START "CDH","OBB_HI_TLM_RATES_2",0,603

Mission Sim 1 Timeline

2001-DEC-6/02:59:39	2003-319/02:59:39	43383515	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-6/02:59:39	2003-319/02:59:39	43383515	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-6/02:59:39	2003-319/02:59:39	43383515	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-6/02:59:39	2003-319/02:59:39	43383515	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-6/02:59:39	2003-319/02:59:39	43383515	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-6/02:59:40	2003-319/02:59:40	43383516	1	USE_REDUNDANT_SS "CDH"
2001-DEC-6/02:59:40	2003-319/02:59:40	43383516	0	CD_TLM_PKT_PROD "SUB_SYS_STAT_PKT","PROD_SEL_RATE",1
2001-DEC-6/02:59:40	2003-319/02:59:40	43383516	0	CD_TLM_PKT_PROD "HOUSEKEEPING_1_PKT","PROD_SEL_RATE",3
2001-DEC-6/02:59:40	2003-319/02:59:40	43383516	0	CD_TLM_PKT_PROD "HOUSEKEEPING_2_PKT","PROD_SEL_RATE",5
2001-DEC-6/02:59:40	2003-319/02:59:40	43383516	0	CD_TLM_PKT_PROD "CDH_PKT","PROD_SEL_RATE",4
2001-DEC-6/02:59:40	2003-319/02:59:40	43383516	0	CD_TLM_PKT_PROD "AUT_PKT","PROD_SEL_RATE",3
2001-DEC-6/02:59:40	2003-319/02:59:40	43383516	0	USE_PRIMARY_SS "CDH"
2001-DEC-6/02:59:40	2003-319/02:59:40	43383516	0	MACRO_END
2001-DEC-6/03:14:29	2003-319/03:14:29	43384405	889	USE_REDUNDANT_SS "SSR"
2001-DEC-6/03:14:29	2003-319/03:14:29	43384405	0	SSR_HI_RCRD_ST "DISABLE"
2001-DEC-6/03:14:29	2003-319/03:14:29	43384405	0	SSR_WRT_PNTR_SV "HIGH",1
2001-DEC-6/03:14:29	2003-319/03:14:29	43384405	0	USE_PRIMARY_SS "SSR"
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	898	USE_REDUNDANT_SS "SSR"
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	CD_DL_INTRLV_SEL "THIRTYTWO"
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	USE_REDUNDANT_SS "CDH"
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	USE_PRIMARY_SS "CDH"
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	USE_REDUNDANT_SS "CDH"
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	AUT_RUL_LOAD 401,15,"DIS","BC_ONLY","MAINT",1,1,"NO_CHAIN",30,30,"VALUE","EQUALS","UNSIGN"
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	EXECUTE_MACRO "OBB_SSR2_PB_SEG_1"
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	AUT_RUL_ST_SET "ENA_AND_WRT_PROTECT",401,401
2001-DEC-6/03:29:27	2003-319/03:29:27	43385303	0	USE_PRIMARY_SS "CDH"
2001-DEC-6/03:29:28	2003-319/03:29:28	43385304	1	USE_PRIMARY_SS "SSR"
2001-DEC-6/07:29:59	2003-319/07:29:59	43399735	14431	USE_REDUNDANT_SS "CDH"
2001-DEC-6/07:29:59	2003-319/07:29:59	43399735	0	AUT_RUL_ST_SET "DIS_AND_WRT_ENABLED",401,410
2001-DEC-6/07:29:59	2003-319/07:29:59	43399735	0	USE_PRIMARY_SS "CDH"
2001-DEC-6/07:30:04	2003-319/07:30:04	43399740	5	USE_REDUNDANT_SS "CDH"
2001-DEC-6/07:30:04	2003-319/07:30:04	43399740	0	CD_DL_SRC_SEL "RT"
2001-DEC-6/07:30:04	2003-319/07:30:04	43399740	0	SSR_PBACK "NUM_BLOCK",0,1
2001-DEC-6/07:30:04	2003-319/07:30:04	43399740	0	USE_PRIMARY_SS "CDH"

[illegible]

[illegible]

[illegible][illegible][illegible][illegible][illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

0.00000000,0.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0523359600000000,0.9986295300000000,0.00

[illegible]

00000000,0.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0523359600000000,0.9986295300000000,0.00

[illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

NED	16",852,0,3,0,0.0000000000000000,"VALUE","NOT_EQUAL","UNSIGNED	16",852,0,1,0,4.0000000000000000,"VALUE","NOT_EQUAL","UNSIGNED	16",852,0,1,0,4.000000
-----	--	--	------------------------

[illegible]

NED	16",852,0,3,0,0.0000000000000000,"VALUE","NOT_EQUAL","UNSIGNED	16",852,0,1,0,4.0000000000000000,"VALUE","NOT_EQUAL","UNSIGNED	16",852,0,1,0,4.000000
-----	--	--	------------------------

[illegible]

[illegible][illegible]

Mission Sim 1 Timelin

[illegible]

0.00000000,0.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0523359600000000,0.9986295300000000,0.00

00000000,0.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0523359600000000,0.9986295300000000,0.00

[illegible]

Mission Sim 1 Timeline

[illegible]

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0523359600000000,0.9986295300000000,0.00

[illegible]

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0523359600000000,0.9986295300000000,0.00

[illegible]

[illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0819385100000000,0.9966373900000000,0.00

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0819385100000000,0.9966373900000000,0.00

[illegible]

Mission Sim 1 Timeline

[illegible]

Page 54

[illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

```
00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0000000000000000,-1.0000000000000000,0.0000000000000000,
```

[illegible]

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0000000000000000,-1.0000000000000000,0.00

[illegible]

[illegible]

[illegible]

[illegible]

[illegible][illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0523359600000000,0.9986295300000000,0.00

)0000000,1.000000000000000,2.000000000000000,0.000000000000000,0.000000000000000,1.000000000000000,0.000000000000000,0.052335960000000,0.998629530000000,0.00													

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0523359600000000,0.9986295300000000,0.00

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0174524100000000,0.9998477000000000,0.00

00000000,1.0000000000000000,2.0000000000000000,0.0000000000000000,0.0000000000000000,1.0000000000000000,0.0000000000000000,0.0174524100000000,0.9998477000000000,0.00

[illegible]

Mission Sim 1 Timeline

[illegible]

NED_16",852,0,3,0,0.0000000000000000,"VALUE","NOT_EQUAL","UNSIGNED_16",852,0,1,0,4.0000000000000000,"VALUE","NOT_EQUAL","UNSIGNED_16",852,0,1,0,4.000000

Mission Sim 1 Timeline

NED	16"	852,0,3,0,0.0000000000000000	"VALUE"	"NOT	EQUAL"	"UNSIGNED	16"	852,0,1,0,4.0000000000000000	"VALUE"	"NOT	EQUAL"	"UNSIGNED	16"	852,0,1,0,4.000000
-----	-----	------------------------------	---------	------	--------	-----------	-----	------------------------------	---------	------	--------	-----------	-----	--------------------

[illegible]

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

Mission Sim 1 Timeline

[illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

[illegible]

Mission Sim 1 Timeline

[illegible]

This image shows a full page of blank graph paper. The grid consists of small, equal-sized squares formed by thin black lines. There are no margins, text, or other markings on the page.

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]

Mission Sim 1 Timeline

[illegible]